

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0735/2022/EQ
DATE : 25-Aug-22
WIP : 38715

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LIM BOON LEONG
ADDRESS : 3 LOR 5 TOA PAYOH
#35-16, GEM RESIDENCES
SINGAPORE 319459
TELEPHONE : HP +65 81574245
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900170790-02
VEHICLE NO : **SMP 5338 E**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 30-09-2019
ENGINE NO : CVK 084478
CHASSIS NO : WAUZZZF45KA090025
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Aug-22
PLACE OF ACCIDENT : PIE TOWARDS TUAS NEAR 36KM/
JALAN BAHAR EXIT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5338 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓ ✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	✓ ✓
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00	1000 ✓
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$ 3,000.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 6,332.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5338 E

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	REAR BUMPER <i>Dented</i>	1	\$ 3,188.00	✓	2550.40	
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 487.00	+		
3	REAR BUMPER SECURING STRIPS ? <i>nec</i>	1	\$ 249.00	?	198.80	
4	REAR BUMPER SPOILER <i>cut</i>	1	\$ 276.00	✓	220.80	
5	REAR BUMPER BLACK TRIM <i>cracked</i>	1	\$ 326.00	✓	260.80	
6	REAR BUMPER BRACKET LH / RH ? <i>nn</i>	2	\$ 260.00	?	x	
7	REAR BUMPER LIGHT REFLECTOR REAR LH / RH <i>new</i>	2	\$ 92.00	+		
8	REAR BUMPER REINFORCEMENT BEAM ? <i>dented</i>	1	\$ 1,131.00	?	904.80	
9	REAR BUMPER SEAL ? <i>nec</i>	2	\$ 32.00	?	25.28	
10	REAR BUMPER GUIDE SECTION LH/ RH <i>new</i>	2	\$ 52.00	+		
11	REAR BUMPER HOLDING STRIPS LH / RH <i>new</i>	2	\$ 188.00	+		
12	REAR PARKING AID SENSORS INNER/ OUTER <i>Inner Misc</i>	21	\$ 531.00		265.50	212
13	REAR PARKING AID SENSORS SEAL RINGS <i>new</i>	4	\$ 10.00	✓	8	
14	EXHAUST TAIL TRIM PIPE LH / RH <i>new</i>	2	\$ 766.00	+		
15	REAR LID <i>Dented</i>	1	\$ 3,497.00	✓	2797.60	
16	REAR LID LOCK	1	\$ 218.00	+		
17	REAR LID LOCK COVER CAP <i>new</i>	1	\$ 8.00	+		
18	REAR LID LOCK STRIKER	1	\$ 37.00	+		
19	PARKING ADHESIVE <i>new</i>	1	\$ 21.00	✓	16.80	
20	REAR LID WEATHERSTRIP <i>new</i>	1	\$ 229.00	+		
SUB TOTAL SPARE PARTS		:	\$ 11,598.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5338 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AUDI CHROME LOGO <i>3 per</i>	1	\$ 144.00	✓ 114.80
22	AUDI CHROME EMBLEM " A4 " <i>3 per</i>	1	\$ 104.00	✓ 82.80
23	REAR NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60
24	SUNDRIES <i>? nec</i>	1	\$ 350.00	? 36
TOTAL SPARE PARTS		:	\$ 12,256.00	
TOTAL LABOUR CHARGES		:	\$ 6,332.00	
GRAND TOTAL		:	\$ 18,588.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adam L
SURVEYED DATE : 29/08/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorized, 05 days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT