

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0735/2022/EQ
DATE : 25-Aug-22
WIP : 38715

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

5 days - ok - Johnny Boo 2 Dec 22

OWNER'S NAME : MR. LIM BOON LEONG
ADDRESS : 3 LOR 5 TOA PAYOH
#35-16, GEM RESIDENCES
SINGAPORE 319459
TELEPHONE : HP +65 81574245
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900170790-02
VEHICLE NO : **SMP 5338 E**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 084478
CHASSIS NO : WAUZZZF45KA090025
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Aug-22
PLACE OF ACCIDENT : PIE TOWARDS TUAS NEAR 36KM/
JALAN BAHAR EXIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5338 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	\$ 280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,500.00	\$ 1,000.00
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$	3,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	6,332.00	\$ 2,932.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5338 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 3,188.00	\$	2,550.40
2	REAR BUMPER FIXING PARTS	1	\$ 487.00		
3	REAR BUMPER SECURING STRIPS	1	\$ 249.00	\$	198.80
4	REAR BUMPER SPOILER	1	\$ 276.00	\$	220.80
5	REAR BUMPER BLACK TRIM	1	\$ 326.00	\$	260.80
6	REAR BUMPER BRACKET LH / RH	2	\$ 260.00		
7	REAR BUMPER LIGHT REFLECTOR REAR LH / RH	2	\$ 92.00		
8	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	\$	904.80
9	REAR BUMPER SEAL	2	\$ 32.00	\$	25.28
10	REAR BUMPER GUIDE SECTION LH/ RH	2	\$ 52.00		
11	REAR BUMPER HOLDING STRIPS LH / RH	2	\$ 188.00		
12	REAR PARKING AID SENSORS INNER/ OUTER	2	\$ 531.00	\$	212.00
13	REAR PARKING AID SENSORS SEAL RINGS	4	\$ 10.00	\$	8.00
14	EXHAUST TAIL TRIM PIPE LH / RH	2	\$ 766.00		
15	REAR LID	1	\$ 3,497.00	\$	2,797.60
16	REAR LID LOCK	1	\$ 218.00		
17	REAR LID LOCK COVER CAP	1	\$ 8.00		
18	REAR LID LOCK STRIKER	1	\$ 37.00		
19	PARKING ADHESIVE	1	\$ 21.00	\$	16.80
20	REAR LID WEATHERSTRIP	1	\$ 229.00		
SUB TOTAL SPARE PARTS		:	\$ 11,598.00	\$	7,195.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5338 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>7,195.28</i>
21	AUDI CHROME LOGO	1	\$ 144.00	\$	<i>114.80</i>
22	AUDI CHROME EMBLEM " A4 "	1	\$ 104.00	\$	<i>82.80</i>
23	REAR NO PLATE	S/N	\$ 60.00	\$	<i>60.00</i>
24	SUNDRIES	1	\$ 350.00	\$	<i>36.00</i>
TOTAL SPARE PARTS		:	\$ 12,256.00	\$	<i>7,488.88</i>
TOTAL LABOUR CHARGES		:	\$ 6,332.00	\$	<i>2,932.00</i>
GRAND TOTAL		:	\$ 18,588.00	\$	<i>10,420.88</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-04/11/22