

1 oct. *NT 22.00.84.11.1.*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G

SHD9299E

Not Authorized
11/8/8650h

AAD2208-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 AUG 2022

SHD9299E

JTDKB3FU803079981

200303878K

TOYOTA

PRIUS

29/08/2022

SKS311Y/AUTO & GEN

17/05/2019

PART

- 1 COVER, FRONT BUMPER
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 LAMP ASSY, FOG, RH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH
- 1 RIM
- 1 KNUCKLE, STEERING, RH
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH
- 1 ABSORBER ASSY, SHOCK, FRONT RH

LIST

- \$ CM 516.00 ✓
- \$ CM 80.10 ✓
- \$ R 716.60 X
- \$ L 79.60 X
- \$ M 951.40 ✓
- \$ M 2,637.60 ✓
- \$ L 29.30 X
- \$ M 219.10 ✓
- \$ L 346.00 X
- \$ M 90.80 ✓
- \$ L 170.10 X
- \$ R 977.80 ✓
- \$ CM 206.70 ✓
- \$ M 54.60 ✓
- \$ M 1,900.10 ✓
- \$ L 663.40 X
- \$ R 760.10 X
- \$ R 438.30 ✓

TOTAL \$ 8,975.80
25% \$ 2,243.95
\$ 6,731.85

Special Nett

FRT BUMPER CLIP

TYRE

FRT NUMBER PLATE WITH HOLDER

FRT BUMPER SIDE RETAINER CLIP

180sn \$ 65.00 ✓
180sn \$ 300.00 907m
\$ 120.00 X
\$ 65.00 X

1956.52
8938.90

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD9299E

AAD2208-

1 FENDER LINER CLIP

\$	1m	75.00	6512
TOTAL \$		625.00	

TOTAL PARTS \$	7,356.85
-----------------------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	8001
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	4~	380.00 X
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	5001
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	1~	170.00 X

TOTAL \$	4,990.00
-----------------	-----------------

Over All Total \$	12,346.85
--------------------------	------------------

(PART-BY-PART) Repair Days 20 Days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Weekend (\$)

TOTAL