

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Authorized
 11 Sing @ 5350/2
 Penny Aka Pamy
 Fday*

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 30.08.2022

Accident Date : 27.08.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota Vios" Reg. No. SJK2602Z Claiming Against Your Insured Veh. No. SLN4847G			
1pc	Boot <i>681.20</i>		<i>RA</i> 871.00 ✓
2pcs	Boot Hinges	65.00	<i>R</i> 130.00 X
1pc	Boot Emblem		<i>na</i> 65.00 —
1pc	Boot Badge VIOS		<i>na</i> 63.00 —
1pc	Boot Badge E		<i>na</i> 54.00 —
1pc	Boot Outer Moulding		<i>map</i> 245.00 —
1pc	Boot Lock		<i>na</i> 123.00 —
1pc	Boot Lock Catch		<i>R</i> 38.50 X
1pc	Boot Stopper RH		<i>na</i> 13.20 —
1pc	Boot Weatherstrip	<i>11312</i>	<i>na</i> 226.00 <i>50212</i>
1pc	Rear Bumper <i>488.10</i>		<i>RA</i> 522.00 —
12pcs	Rear Bumper Clips	5.00	<i>na</i> 60.00 —
1pc	Rear Bumper Bracket RH		<i>dit</i> 121.00 —
2pcs	Rear Bumper Top Retainers	97.00	<i>disdit</i> 194.00 <i>LT</i>
2pcs	Rear Bumper Reflectors <i>e105.40</i>	150.00	<i>djcm</i> 300.00 <i>LT</i>
2pcs	Rear Bumper Corner Retainers	90.00	<i>disdit</i> 180.00 <i>LT</i>
2pcs	Taillamps <i>e355.10</i>	372.00	<i>CMA</i> 744.00 <i>110.70</i>
2pcs	Taillamp Gaskets	25.00	<i>na</i> 50.00 —
2pcs	Taillamp Panels	159.00	<i>d1RA</i> 318.00 <i>LT</i>
1pc	End Panel <i>655.10</i>		<i>RA</i> 764.00 —
1pc	End Panel Garnish <i>165.80</i>		<i>CMA</i> 242.00 —
1pc	Spare Tyre Top Board		<i>dit</i> 164.00 —
2pcs	Boot Compartment Storage Styrofoam Boards <i>e142.10</i>	283.00	<i>CMA</i> 566.00 <i>284.20</i>
1pc	Rear Fender RH	1,070.00	<i>R</i> 900.00 X
1pc	Rear Joint Panel (Taillamp-Fender)		<i>RA</i> 198.00 —
2pcs	Rear Fender Trim Boards <i>e15 defum</i>	285.00	570.00 <i>LT</i>
1pc	Rear Windscreen Moulding		<i>na</i> 155.00 —
1pc	Rear Exhaust Silencer <i>585</i>		<i>RA</i> 820.00 <i>Z</i>
1pc	Rear Exhaust Silencer Gasket		<i>na</i> 42.00 <i>Z</i>
	Less 25%		8,738.70
			2,184.68
			6,554.03
	Rear Number Plate	<i>na</i>	<i>RA</i> 45.00 SN ✓
	Rear Bumper Reverse Sensor		<i>26WIN</i> 280.00 SN
	Rear Windscreen Sealant		<i>na</i> 50.00 SN X
	Rear Windscreen Sealer		<i>na</i> 40.00 SN X
	Rear Windscreen Fastener		<i>na</i> 50.00 SN X
	Roadside Assist Signage		<i>CM</i> 45.00 SN ✓
	Portable Vacuum Cleaner		<i>NA</i> 110.00 SN X
		CIF	7,174.03

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 30.08.2022

Accident Date : 27.08.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Vios" Reg. No. SJK2602Z Claiming Against Your Insured Veh. No. SLN4847G		
		B/F	7,174.03
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring etc.		120.00 <i>50d</i>
	To Dismantle / Refit Rear Windscreen Glass		<i>na</i> 160.00 <i>X</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 <i>✓</i>
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories		100.00 <i>50d</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>60d</i>
	To Repair / Replace & Align Muffler / Exhaust System		120.00 <i>60d</i>
	To Supply End Panel / Rear Fender Body Joint Sealant		<i>na</i> 80.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis, Inner Panel, Floor Panel, Spare tyre Panel, Rear N/S Fender etc. Cnt, Weld End Panel, Rear Fender & Part Replacement		1,800.00 <i>1000d</i>
	To Spray Painting Affected Areas (Rr Fender, Taillamp Panels *2, End Panel, Spare Tyre Panel Boot, Boot Garnish, Bumper, Bumper Sensors. Joint Panels *2 Etc...)		<i>1000d</i> 1,800.00
		Total :	<u>11,534.03</u>

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: