



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAY HAN QIN, GALVIN MARC (ZHENG HANQIN) BLK 904 JURONG WEST STREET 91 #10-149 SINGAPORE 640904 Contact No Mobile: 83228204	Cust No/Name /TAY HAN QIN, GALVIN MARC (ZHENG Reg No/Reg Date SJU2282K / 17/01/202 Date In/Mileage / 0 Chassis No KNAF3416ML5060238 Engine No G4FGKH739813 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	29/08/2022/ 17:50	TLE	261 / Edwin Caina	56483			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW RR BUMPER							2240.00
	REPAIR RR END PNL & BOOTLID							640
E PNT98000	RESPRAY RR BUMPER , RR END PNL & BOOTLID							550 1650.00
E PNT88000	REMOVE & REFIT RR FLR BOARD , TRIM & CARPET							X 280.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM							80.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							280.00
E PNT88000	REMOVE & REFIT REVERSE SENSOR							80 100.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS							X 120.00
M SUNDRY	SUPPLY C&C BADGE							X 50.00
M SUNDRY	Sundries							20 50.00
M SUNDRY	SUPPLY REVERSE SENSOR							A 280.00
M COVER-RR BUMPER	X R				1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR	X CUT				1.00	241.00	00.00	241.00
M EXTN WIRING ASSY-BWS	X NN				1.00	207.00	00.00	207.00
M BEAM-RR BUMPER	X NN				1.00	318.00	00.00	318.00
M STAY-RR BUMPER LH	X NN				1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH	X NN				1.00	65.00	00.00	65.00
M COVER-RR BUMPER FOG LAMP,LH	X NN				1.00	19.00	00.00	19.00
M COVER-RR BUMPER FOG LAMP,RH	X NN				1.00	19.00	00.00	19.00
SURVEYOR NAME : Steve (LKK)								
SURVEYOR SIGNATURE : 7/10/22, 11.00.00								

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 7/10/22, 11.00

Confirm & accepted by
LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

DATE: 7/10/22

REMARKS: PIP

17 BL 0% GST on

Total Payable

Nett 6,715.00

470.05

7,185.05

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.