

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg
 India International Insurance Pte Ltd (HQ)
 205 Braddell Road
 Singapore 579701
 (Co. Reg No: 199506048W)

Particulars of Claim

Type:
 No:
 Reg. No:
 Info:
 Involved

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
 Tel : 64817221

L H Car Rental Pte Ltd
 Blk 5038 #01-405
 Ang Mo Kio Industrial Pk 2
 Singapore 569541

Vehicle No : SLQ 7330 U
 Make : Toyota C-HR
 Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy		\$1,250.60	✓
1 pc	Rear tail-gate glass moulding		\$95.20	✓
1 pc	Rear tail-gate inner trim board		\$426.50	X
1 pc	Rear tail-gate outer garnish		\$925.60	X
1 pc	Rear tail-gate inner lock		\$452.70	X
1 pc	Rear tail-gate emblem - Hybrid		\$48.90	X
1 pc	Rear tail-gate emblem - C-HR		\$45.80	X
1 pc	Rear boot rubber		\$205.60	X
1 pc	Rear bumper		\$855.60	✓
1 pc	Rear bumper reinforcement		\$483.20	✓
1 pc	Rear lower bumper		\$455.70	✓
2 pcs	Rear bumper side retainer	\$75.10	\$150.20	X
1 pc	Rear tow cover		\$55.10	X
1 pc	Rear antenna		\$175.20	✓
1 pc	Rear end panel		\$725.70	X
1 pc	Rear end panel inner garnish		\$355.70	X
			\$6,707.30	
			Less 25 %	
			\$1,676.83	
			\$5,030.47	

S Nett

20 pcs	Rear bumper clip	\$2.00	\$40.00	✓
1 pc	Rear reverse sensor		\$200.00	✓
1 pc	Rear windscreen sealant		\$40.00	✓
			\$280.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting. \$1,200.00 500
 To putty & spray paint on accident affected portion \$1,200.00 600
 balance c/f \$7,710.47

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Not Authorised
 1/By 83000h
 Melway After Paint
 4 days

2YX10

545.10 399.50

500

600

3.21.2020 11:11

SLQ 7330 U

balance b/f \$7,710.47

Labour Charges

Check and reconnect wiring

\$40.00

15/

To anit- rust proofing

\$120.00

30/

Remove/refit rear windscreen

\$120.00

✓

Total

\$7,990.47

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: