

Xin Yu (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Monday, 5 September 2022 4:14 PM
To: Xin Yu (LKK Auto)
Subject: Re: File Audit - SHC 4882J & SMB 8032R & GBL 3912H & SKV 3983Y & SKC 323Y

Dear Xin Yu,

Audit check done for SHC4882J, SMB8032R, GBL3512 & SKV3983Y without problem, SKC323Y found no wheel alignment report upload.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Xin Yu (LKK Auto) <xinyu@lkkauto.com>
Sent: Monday, 5 September 2022 2:56 pm
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: File Audit - SHC 4882J & SMB 8032R & GBL 3912H & SKV 3983Y & SKC 323Y

Dear Simon,

File for Audit Check.

1. SHC 4882J - NS/INC22006757/Rc
2. SMB 8032R - NS/INC22008425/Rc
3. GBL 3912H - CS/INC22008094/Kcy3
4. SKV 3983Y - CS/CTI22007489/Kcy3
5. SKC 323Y - CS/ASM22007450/Kcy3

Thanks and Warmest Regards,

Xin Yu

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: XinYu@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)