

SMRT Automotive Services Pta Ltd 80 Woodlands Industrial Plank E4, Singapore 757705 FAX Number - 63685692 Estimator Telephone Number - 66662623 Accident Reporting Number - 68662672

Date Generated : 18/07/2022 User ID : JeongCH

	Section A - A	ccident Details		
stration Number	SM88032R	THE RESERVE OF THE PARTY OF THE	1000 P. COLUMN S. C. W. C. A. C. S. C. S.	
Reference Number	BUS/07/22/5007			
estration Date	10/5/2015		A Service Management	ALLE STATE OF THE PARTY OF THE
mpany Type	SMRT Buses Ltd			
Ka	WAN			
odel	A22			
ame of Driver	NG BOON CHEW			
ype of Accident	Side Swipe		******	
ocident Date and Time	7/6/2022 7:32 PM			
scrident Reported Date and Time	7/6/2022 1:45 PM			
s Surveyor Required?	No			
survey by		ter a se francisco do como en torico de la contra		
Fehicle is Towed Back?	No			
owed Back Date and Time	The state of the s			
ceptacement Venicle issued?	No			
tob Card Number				
loucial instruction to ARC if any	SM84032R - 9 ces he	adjects cover cracked		
	SMB8032R - Right he SGV1099K (TP) - INS	URED WITH NTUC		
Prepared Date and Time	7/15/2022 6:30 PM			
Trassis Number	WMAA24ZZ8F700273	15		
Migage				
Vork Shop				
Tepair Completion Date and Time				
HAVE AND THE PARTY OF THE PARTY	Section B - Summa	ry of Repair Estima	tos	Carry St. As was hard
lummary of Repair Estimates		CALCOT POLICIAL	NAME OF THE PARTY	
	Quotation from ARC		Adjusted by Surve	eyor, if applicable
otal Labour Cost	\$1,590.00		10.00	
otal Spray Cost	\$1,048.00	THE RESERVE OF THE PERSON OF T	0.00	
Olial Spana Part Cost	\$3,134.43		50.00	
otal Other Cost	\$0.00	**************************************	10.00	
OTAL COST	\$5,772.43		0.00	
ump Som Total	\$0.00		0.00	No. 3 April 1985
Jumber of Repair Days	4.0		3 2045	management of the second second section is
'repared / Adjusted By	Jeong Choon Hwee		2003	FILLET SCHOOL
-RC / Surveyor Sign Off Date	15/07/2022 7:31 PM			A SHEET CLEENING
lignature 1	1	Parkett State of the State of t		Consideration of the
				TOWN DESIGNATION OF THE PARTY O
				All And And
	STREET, STREET	THE RESIDENCE OF THE PARTY OF T		
			BOALSHISHDAMP STRAIGSEN AT	國際海域於 宋 四人的公司公司 1807回至4年21
temarks	The Control of the Control		Treatment of the second	termine
(emarks				two-many
temarks				twinter on the
	Section C - Quotation			two-many
	Section C - Quotation an	nd Accident Invoice		twinter on the
Nuclation Number	Section C - Quotation an	Invoice Humber		twinter on the
TERRIA .	Section C - Quotation ap	and the same		twinter on the



19.12.2

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pie Lie 60 Woodlands Industrial Park E4, Singapore FAX Number 83885592 Estimator Telephone Number 68662623 Accident Reporting Number 58662672

Date Generated: 18/07/2022

: JeongCH User IO

Section D - Details of Repair Estimates art 1 - Labour Works Adjusted by Surveyor, if applicable Quotation from AR b Scope 1325 O REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS AMAGED AFFECTED AREAS. \$1,590.00 \$1,590.00 2203 art 2 - Spray Painting & Panel Beating Related Works Adjusted by Surveyor, if applicable Quotation from ARC ob Scope 878 ROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS \$1,048.00 \$1,048.00 otal Spray Painting & Panel Beating art 3 - Other Costs - Accident and Accident Repair Related Expense Adjusted by Surveyor, if applicable Quotation from ARC ob Scope otal Other Costs

art 4 - Spare	Parts / Mate	THE RESERVE OF THE PARTY OF THE		-		1	1-1-1-1-1	E-waster & constructed	Surveyor Approved
art Number	Portion	Stock Number	Part Name	Quantity	List Price (3)	Discount (%)	Final Price (3)	Estended Approves	But 1990 App of the
010152	Body	F01001-CW266	COVER HEADLAMP FRT	1.00	\$974.70	10.00	\$877.23	Replace	bur
010305	VE	81.25101-6540	HEADLAMP, RH (MAN BUS)	1.00	\$1,903.60	10.00	\$1,443.24	Replace	100/
010307	W.		FLASHER, AUX HEADLAMP, RH (MAN BUS)	1.00	\$904.40	10.00	5813.96	Replace	100
010154	Body	F01001-CW263	FLAP, FRONT FOR MAN A22 BUS	1.00	\$1,668.80	100.00	\$0.00	Repair	R
010073	Body	F01001-CW262	DOME FRONT FOR MAN A22 BUS	1,00	\$2,817.50	100.00	\$0.00	Repair	l K
010151	Body		BUMPER FRONT CENT RE FOR MAN A22 BUS	1 00	\$1,868.80	100.00	\$0.00	Repair	R
otal	and the second				\$10,037,80		\$3,134.43		

idded Spare Parts / Material	is / Material Usage After Surveyor Signed Oil								
art Number Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
otal									

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged gart(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3134.43 RAML
3134.43 RAML
67.32 Hp 20010068

5404175 3 days
20% Lls
4323.80 Lls
18/07/22 P1435
5-94,300 Rosy after april

age 2 of 2

SMRT Automotive Service

60 Woodlands Industrial Par

FAX Number : 63685592

Estimator Telephone Number

Accident Reporting Number

Date Generated: 26/08/

User ID

: Cathe

Section D - Details of Repair Estimates					
	Quotation from AR	Adjusted by Surveyor, if applicable			
ABOVE ITEMS AND REPAIR OTHERS S.	\$1,590.00	\$1,325.00			
	\$1,590.00	\$1,325.00			

Panel Beating Related Works

	Quotation from ARC	Adjusted by Surveyor, if applicable
TERIAL TO PUTTY AND RESPRAY ABOVE	\$1,048.00	\$878.00
el Beating	\$1,048.00	\$878.00

ident and Accident Repair Related Expense

	Quotation from ARC	Adjusted by Surveyor, if applicable
veyor	\$0.00	(\$440.60)
	\$0.00	(\$440.60)

erial Usage

Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
F01001-CW266	COVER, HEADLAMP: FRT ,RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
81.25101-6540	HEADLAMP,RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
81.25320-6112	FLASHER,AUX HEADLAMP,RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	Replace
F01001-CW263	FLAP,FRONT:FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
F01001-CW262	DOME:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	Repair
TO CAR CONTRACTOR AND DESCRIPTION OF THE PROPERTY OF THE PROPE	BUMPER, FRONT: CENT RE, FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
			\$10,037.80		\$3,134.43		

rial Usage After Surveyor Signed off

Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
	RETAINER:MALE & FEMALE,REAR LID,MAN BUS	1.00 bt	\$74.80	10.00	\$67.32	Replace	Replace
			74.80		67.32		



SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 26/08/2022
User ID : CatherineLee

	Section A - Acciden	t Details					
Registration Number	SMB8032R						
Case Reference Number	BUS/07/22/5007						
Registration Date	5/10/2015						
Company Type	SMRT Buses Ltd	RT Buses Ltd					
Make	MAN	V					
Model	A22	A22					
Name of Driver	NG BOON CHEW						
Type of Accident	Side Swipe						
Accident Date and Time	6/7/2022 7:32 PM						
Accident Reported Date and Time	6/7/2022 1:45 PM						
Is Surveyor Required?	Yes						
Survey by							
Vehicle is Towed Back?	No						
Towed Back Date and Time							
Replacement Vehicle issued?	No						
Job Card Number	24115639						
Special Instruction to ARC,if any	SMB8032R - Right headlight co SGV1099K (TP) - INSURED WI	ver cracked TH NTUC					
Prepared Date and Time		15/7/2022 6:30 PM					
Chassis Number	WMAA24ZZ8F7002735						
Mileage							
Repair Completion Date and Time	Section B - Summary of Re	pair Estimates					
Repair Completion Date and Time	Section B - Summary of Re	pair Estimates Adjusted by Surveyor, if applicable					
Repair Completion Date and Time Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost		Adjusted by Surveyor, if applicable					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost	Quotation from ARC \$1,590.00	Adjusted by Surveyor, if applicable					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spray Part Cost	Quotation from ARC \$1,590.00 \$1,048.00	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60)					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spray Part Cost Total Other Cost TOTAL COST Lump Sum Total	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40 \$0.00	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80 \$4,300.00					
Work Shop Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40 \$0.00 4.0	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80 \$4,300.00 3.0					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spray Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40 \$0.00 4.0 Jeong Choon Hwee	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80 \$4,300.00 3.0 Rasul					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40 \$0.00 4.0 Jeong Choon Hwee 15/07/2022 7:31 PM	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80 \$4,300.00 3.0 Rasul 18/07/2022 3:47 PM					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40 \$0.00 4.0 Jeong Choon Hwee 15/07/2022 7:31 PM	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80 \$4,300.00 3.0 Rasul 18/07/2022 3:47 PM					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spray Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature Remarks	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40 \$0.00 4.0 Jeong Choon Hwee 15/07/2022 7:31 PM S Section C - Quotation and Accide	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80 \$4,300.00 3.0 Rasul 18/07/2022 3:47 PM					
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	Quotation from ARC \$1,590.00 \$1,048.00 \$2,561.40 \$0.00 \$5,199.40 \$0.00 4.0 Jeong Choon Hwee 15/07/2022 7:31 PM S Section C - Quotation and Accide	Adjusted by Surveyor, if applicable \$1,325.00 \$878.00 \$2,561.40 (\$440.60) \$4,323.80 \$4,320.00 3.0 Rasul 18/07/2022 3:47 PM					



SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 26/08/2022
User ID : CatherineLee

			Secti	on D - Det	ails of Repair E	stimates				
Part 1 - Labo	ur Works			on b - bet	ans of Repair E	Stilliates				
Job Scope				Quotation	from AR			Adjusted by Surveyo	or, if applicable	
TO REMOVE &	INSTALL ALL	ABOVE ITEMS AND	REPAIR OTHERS	\$1,590.00			\$1,325.00			
Total Labour	FECTED AREA			\$1,590.00				\$1,325.00		
Part 2 - Spra	y Painting & F	Panel Beating Rela	ated Works							
Job Scope				Quotation	from ARC			Adjusted by Surveyo	or, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS								\$878.00		
	ainting & Panel	l Beating		\$1,048.00				\$878.00		
Part 3 - Othe	r Costs - Acci	dent and Acciden	t Repair Related Expens	se						
Job Scope					rom ARC	Adjusted by Surveyor, if applicable				
Lump Sum Adjustment by Surveyor				\$0.00				(\$440.60)		
Total Other Co	sts			\$0.00				(\$440.60)		
Part 4 - Spare	Parts / Mate	rial Usage								
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace	
6010305	VE	81.25101-6540	HEADLAMP,RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace	
6010307	VE	81.25320-6112	FLASHER,AUX HEADLAMP,RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	Replace	
6010154	Body	F01001-CW263	FLAP,FRONT:FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair	
5010073	Body	F01001-CW262	DOME:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	Repair	
6010151	Body	F01001-CE265	BUMPER,FRONT:CENT RE,FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair	
Total					\$10,037.80		\$3,134.43			
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
6009375	VM		RETAINER:MALE & FEMALE,REAR LID,MAN BUS	1.00	\$74.80	10.00	\$67.32	Replace	Replace	