

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 26 Jun 2023

## **Preliminary Advice**

Insured Vehicle No	: PC3494H		
TP Vehicle No	: SDS6883G	Accident Date	: 28/08/2022
Make	: TOYOTA LEXUS	Assignment Date	: 01/09/2022
Date of Inspection	: 30/08/2022	Est. Duration of Repair	: 07
Inspection At	: KANG AUTO ENGINEERING PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,502.75
Revised Amount	:S\$	8,765.82
Check Items (Estimated)	:S\$	
Total	:S\$	8,765.82
Lump Sum Repair	:S\$	7,000.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on "Without Prejudice" basis.  
Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.