

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3084/08/22

Your Ref: *To display damaged part(s) during resurvey*
Resurvey are subject to confirmation

Date: 30th AUG 2022

The Claim's Manager
Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE. LTD.

64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by the Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name Of Insured : Mr Low Boon Keng

Date Of Accident : 27/08/22 (19:08hrs)

Policy Number : D22MPC0002769

Not Admitted
du
2/5 7300
Express
6 days
Whistleblower

Estimate cost of repair to HYUNDAI ELANTRA (A) 1.6 GLS Saloon - SLS 2960 Z

1 pc front bonnet	<i>BUC</i>	\$ 2,253.80	✓
1 pc front bonnet n/s hinge	<i>n</i>	49.00	x
15 pcs front bonnet insulator clips	<i>ner</i>	52.50	✓
1 pc front n/s fender	<i>BUC</i>	1,227.00	✓
1 pc front n/s fender inner shield	<i>Toi</i>	85.00	✓
6 pcs front n/s fender inner shield clips	<i>ner</i>	21.00	✓
1 pc front bumper	<i>Dis</i>	474.00	✓
10 pcs front bumper clips	<i>ner</i>	35.00	✓
1 pc front bumper n/s side retainer	<i>one</i>	38.00	✓
10 pcs front bumper rivets	<i>ner</i>	40.00	✓
1 pc front bumper reinforcement	<i>BUC</i>	695.00	✓
1 pc front bumper sponge damper	<i>Toi</i>	110.00	✓
1 pc front bumper n/s fog lamp comp. set.	<i>one</i>	365.00	✓
1 pc front bumper n/s fog lamp garnish	<i>Dis</i>	115.00	✓
1 pc front grille	<i>ACRE</i>	529.00	✓
6 pcs front grille clips	<i>17</i>	21.00	x
1 pc front grille rubber	<i>ner</i>	26.00	✓
1 pc front grille 'H' logo emblem	<i>17</i>	29.00	x
1 pc n/s hear lamp comp set	<i>320</i>	1,198.00	✓
1 pc n/s head lamp lower bracket	<i>one</i>	28.00	✓
1 pc front support panel	<i>one</i>	949.00	✓
1 pc front support panel top garnish	<i>maped</i>	80.00	✓
6 pcs front support panel top garnish clips	<i>10</i>	21.00	x
1 pc air intake hose assy	<i>BRD</i>	114.00	✓
1 pc front n/s side mirror comp set	<i>cut/eye</i>	638.00	✓

\$ 9,193.30

Less 20%

\$ 1,838.66

\$ 7,354.64

To wiring check up & adjust headlight alignment.

40.00 *20*

To remove & refix & top up air cond gas & necessary parts.

130.00 *100*

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.

1,350.00 *800*

To putty & respray painting on all affected accident parts.

1,500.00 *1000*

HUP MOTOR TRADING & SERVICE

\$ 10,374.64

Dollars : Ten Thousand Three Hundred Seventy Four And Cents Sixty Four Only.

8420.30
6744.24
1920
8664.24

9073.3
7342