

Plate Number	Case Number	Brand	Model Details	Body Type	Insurance company
SLS2960Z	-	Hyundai	Elantra	Sedan	India International Insurance
Technician	SA	Parts Manager			
-	LKK_assignments	-			

No data

Remarks 1 remarks

Pre Review done base on survey information provided

Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic

Amount : \$8664.24

Lump sum: \$6900.00

Repair Duration: 6 days

---