50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO:

AZAHAR BIN MAT YUSOF,

C/O: MOTOCRAFT

#01-18 SINGAPORE 627608

7 SOON LEE STREET

Our Reference:

0122/MC029

Date:

10-Feb-2022

ASSESSMENT OF VEHICLE NO. AZ 9389 X

DATE OF LOSS:

11-Jan-2022

We have carried out a physical assessment at MOTOCRAFT, 7 Soon Lee Street, 01-18 Singapore 627608, according to your instruction

12-Jan-2022

and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.:

AZ 9389 X

Make & Model:

YAMAHA AEROX GDR155A CVT ABS

Year of Registration:

2020

Engine Capacity:

155

Chassis No.:

MH3SG4640LJ072260

Engine No.:

G3J8E0149636

Colour:

BLUE

2. VEHICLE CONDITION

GOOD

Steering:

SERVICEABLE

Foot Brake:

SERVICEABLE

Parking Brake:

SERVICEABLE

Modification:

NIL

3. TYRE PARTICULARS & CONDITION

Front

Make/Size/Thread:

MAXXIS 110/80 R14 - 75%

Rear

Make/Size/Thread:

MAXXIS 140/70 R14-75%

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

5. REMARKS

Market Value:

Na

Salvage Value:

Na

Repair Limit:

Na

Estimated Amount:

\$6,937.30

Adjusted Amount:

\$6,747.30

--- | Adjusted Sum:


\$5,500.00

nated Repair Days:

18 days

Date of Completion:

07-Feb-2022



Pursuant to your instruction, we have NOT AUTHORISED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. AZ 9389 X

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	SIDE MIRROR L/R - SET	Cut	120 🗸 168.00	168.00
1	FRONT HANDLE BAR	Bent	175 🗸 220.00	220.00
1	FRONT HANDLE BALANCER L/R -SET	Cut	60 🗸 96.00	96.00
1	FRONT HANDLE BAR BRACKET	Bent	NN 148.00	
2	FRONT HANDLE BAR GRIP L/R - SET	Cut	NN 82.00	
1	FRONT HEAD LAMP ASSY	Cracked	422.00	
1	FRONT HEAD LAMP STAY	Bent	NN 188.00	
1	FRONT SIGNAL LIGHT L/R - SET (LH only)	Cracked	80 🗸 280.00	280.00
1	FRONT FORK ASSY - SET	Bent	800 🗸 962.00	
1	FRONT FORK UNDER BRACKET	Bent	165.00	
	STEERING CONE BEARING - SET	Jammed	92.00	•
1	FRONT WHEEL AXLE & NUT - SET	Bent	45 🗸 85.00	85.00
1	FRONT WHEEL - SET	Bent	300 🗸 385.00	385.00
1	FRONT WHEEL BEARING - SET	Jammed	30 🗸 65.00	65.00
1	FRONT WHEEL OIL SEAL - SET	Necessary	20 🗸 35.00	35.00
1	FRONT WHEEL CENTRE BUSH	Necessary	15 🗸 30.00	30.00
1	FRONT WHEEL COLLAR - SET	Jammed	15 🗸 30.00	30.00
1	FRONT ABS BRAKE DISC	Bent	NN 195.00	
1	BODY COVERSET 'YAMAHA' LOGO	Necessary	35 🗸 48.00	48.00
1	BODY BLUE COVERSET - SET	Cracked	350 🗸 720.00	720.00
1	BODY INNER MATT COVERSET - SET	Cracked	250 🗸 480.00	
1	FOOTREST BOARD L/R - SET	Cracked	180 🗸 240.00	240.00
1	STEP RUBBER - SET	Cracked	NN 98.00	
		10%	5,234.00	5,234.00
		Less 5% discount	261.70	261.70
		Parts Total:	4,972.30	4,972.30

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. AZ 9389 X

SPECIAL NETT ITEMS

1 FRONT WHEEL TYRE

FRONT WHEEL TUBELESS VALVE - SET

Cut Necessary 160.00 X 160.00

NN

45.00 15 / 45.00

Special Nett Total:

205.00 205.00

LABOUR

s/N	Description		Workshop's Estimate	Our Assessment	
1	Towing charge.		50.00	√ 50.00	
2	Check wiring system and light.		100.00	30 🗸 80.00	
3	Front & Rear wheel ailgnment.		160.00	50 🗸 140.00	
4	To repair, align and balance body main frame		450.00	200√400.00	
5	Labour for repair and replace parts .		1,000.00	250 \sqrt{900.00}	
		Labour Total :	1,760.00	1,570.00	
		TOTAL (PARTS & LABOUR) \$	6,937.30	6,747.30	

workshop has agreed to undertake the repair cost of the final adjusted Sum contract amount is

\$5,500.00

(SINGAPORE DOLLARS FIVE THOUSAND FIVE HUNDRED ONLY)

4 days

