

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way

#07-16, Singapore 079120

GST Ref. No: M2-0111811-5

Vehicle No: SMX 5278C

Chasis No : W0V7D9EB7L4426613

Engine No: 10Z1AE0030964

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
1	1	RR BUMPER CENTRE	1120.00
2	1	RR BUMPER CENTER RETAINER	164.00
3	1	RR BUMPER LOW BRACKET CENTRE RH	95.00
4	1	RR BUMPER LOW BRACKET CENTRE LH	95.00
5	1	RR BUMPER REINFORCEMENT	703.00

Total: 2177.00

Less 10%: 217.70

Parts Total : 1959.30

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair	650.00
2	Remove and replace reverse sensor (Labour)	50.00

Labour Total : 700.00

Sub Total : 2659.30

GST (7%) 186.15

Grand Total: 2845.45

Yours Faithfully,

Ronnie Tan
Service Advisor

Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.