

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22008442/TPA3Q2**Date:** 18/02/2023**REFERENCE**

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900070250-03 |
| <b>Claimant Vehicle No :</b> | FBS2276J                             | <b>Insured Vehicle No :</b> | GBH2851G      |
| Date of Loss:                | 30/08/2022                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 1012765092SG  |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>FBS2276J</b>                   | Engine No:  | G3L8E0334453      |
| Make & Model:               | YAMAHA NMAX155, 155cc ABS CVT     | Chassis No: | MH3SG5680MK058709 |
| Reg. Date:                  | 25/02/2021 (Man. Year: 2021)      | Odometer:   | 84728 km          |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 155 cc                            |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 110/70 R13  | Rear Tyre Size:  | 130/70 R13  |
| Front Left Side:  | Maxxis 5 mm | Rear Left Side:  | Maxxis 5 mm |
| Front Right Side: | 0 mm        | Rear Right Side: | 0 mm        |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 4,374.00          | 3,788.10          | 585.90            | 13.40         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 480.00            | 380.00            | 100.00            | 20.83         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b>                        | <b>4,854.00</b>   | <b>4,168.10</b>   | <b>685.90</b>     | <b>14.13</b>  |
| <b>+ Loss of Use (3.0 x S\$30.00/day) (S\$)</b> |                   | 90.00             |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>4,258.10</b>   |                   |               |

**INSPECTION**

|                             |            |                                                                                                   |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 17/10/2022 |                                                                                                   |
| Date Inspected:             | 17/10/2022 | Inspected At: Pang Scooter Service (HQ)<br>BLK 1006 BUKIT MERAH LANE 2 #01-06<br>Singapore 159762 |
| Estimated Period of Repair: | 3.0 days   |                                                                                                   |

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars            | Condition     | Repairer's | Amount     |
|-----|-----|----------|------------------------|---------------|------------|------------|
| 1   | 1   |          | *HANDLE BAR            | Bent          | 120.00 F   | *120.00 FL |
| 2   | 1   |          | *L/H BRAKE LEVER       | Cut           | 45.00 F    | *45.00 FL  |
| 3   | 1   |          | *SIDE STAND            | Dented        | 65.00 F    | *65.00 FL  |
| 4   | 1   |          | *HANDLE END            | Cut           | 35.00 F    | *35.00 FL  |
| 5   | 1   |          | *HEADLIGHT ASSY        | Cut           | 480.00 F   | *480.00 FL |
| 6   | 1   |          | *FRONT FENDER          | Cut           | 168.00 F   | *168.00 FL |
| 7   | 1   |          | *FRONT WHEEL RIM       | Dented        | 380.00 F   | *380.00 FL |
| 8   | 1   |          | *FRONT WHEEL SHAFT     | Bent          | 35.00 F    | *35.00 FL  |
| 9   | 1   |          | *L/H SIGNAL LIGHT ASSY | Cut           | 95.00 F    | *95.00 FL  |
| 10  | 1   |          | *BIKE CAMERA           | Distorted     | 380.00 F   | *380.00 FL |
| 11  | 1   |          | *UNDER BRACKET         | Bent          | 285.00 F   | *285.00 FL |
| 12  | 1   |          | *STEERING CON          | Bent          | 150.00 F   | *150.00 FL |
| 13  | 1   |          | *FORK ASSY             | Bent          | 485.00 F   | *485.00 FL |
| 14  | 1   |          | *VISOR                 | Cut           | 185.00 F   | *185.00 FL |
| 15  | 1   |          | *L/H MIRROR            | Cut           | 45.00 F    | *45.00 FL  |
| 16  | 1   |          | *FRONT PANEL           | Cracked       | 168.00 F   | *168.00 FL |
| 17  | 1   |          | *L/H LOW SIDE PANEL    | Cut           | 198.00 F   | *198.00 FL |
| 18  | 1   |          | *L/H SIDE PANEL        | Cut           | 215.00 F   | *215.00 FL |
| 19  | 1   |          | *L/H SIDE COVER        | Cut           | 235.00 F   | *235.00 FL |
| 20  | 1   |          | *CENTER PANEL          | Not Necessary | 165.00 F   | *- FL      |
| 21  | 1   |          | *HEAD LIGHT STAY       | Bent          | 160.00 F   | *160.00 FL |
| 22  | 1   |          | *MAIN STAND            | Bent          | 120.00 F   | *120.00 FL |
| 23  | 1   |          | *SIDE STAND            | Bent          | 65.00 F    | *65.00 FL  |
| 24  | 1   |          | *BELT COVER            | Cut           | 95.00 F    | *95.00 FL  |

F=Franchise part. L=ListItemDisc.

|                                                   |          |          |
|---------------------------------------------------|----------|----------|
| Sub Total (S\$)                                   | 4,374.00 | 4,209.00 |
| - List Item Discount on L Items 0.00/10.00% (S\$) | 0.00     | 420.90   |
| Total Parts (S\$)                                 | 4,374.00 | 3,788.10 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars | Lab.Type | Repairer's    | Amount        |
|--------------------------------|-------------|----------|---------------|---------------|
| <b>Labour Items</b>            |             |          |               |               |
| 1                              | TSB         | New      | 80.00         | 80.00         |
| 2                              | LABOUR      | New      | 400.00        | 300.00        |
| <b>Gross Labour Cost (S\$)</b> |             |          | <b>480.00</b> | <b>380.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >