

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBS2276J

DATE ACCIDENT : 30/08/2022

MAKE / MODEL : NMAX 155

S/No	DESCRIPTION	AMOUNT
1	HANDLER BAR	\$ 120.00
2	L/H BRAKE LEVER	\$ 45.00
3	SIDE STAND	\$ 65.00
4	HANDLER END	\$ 35.00
5	HEADLIGHT ASSY	\$ 480.00
6	FRONT FENDER	\$ 168.00
7	FRONT WHEEL RIM	\$ 380.00
8	FRONT WHEEL SHAFT	\$ 35.00
9	L/H SIGNAL LIGHT ASSY	\$ 95.00
10	BIKE CAMERA	\$ 380.00
11	UNDER BRACKET	\$ 285.00
12	STEERING CON	\$ 150.00
13	FORK ASSY	\$ 485.00
14	VISOR	\$ 185.00
15	L/H MIRROR	\$ 45.00
16	FRONT PANEL	\$ 168.00
17	L/H LOW SIDE PANEL	\$ 198.00
18	L/H SIDE PANEL	\$ 215.00
19	L/H SIDE COVER	\$ 235.00
20	CENTER PANEL	\$ 165.00
21		
22	TSB	\$ 80.00
23	LABOUR	\$ 400.00
Total		\$ 4,414.00

Tan Jien 97415777

WP 17/10/22 0530pm

Tan Jien e/ikanto.com

3 days - 4 days

Resurvey before/after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledge by Repairer

Signature:

Date: