

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22008443/EPA3Q2
Date: 26/10/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210044385
Claimant Vehicle No :	FZ9325X	Insured Vehicle No :	SCJ882H
Date of Loss:	22/10/2021	Nature of Claim:	TP
		Claim No:	6868567074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FZ9325X	Engine No:	5YP703324
Make & Model:	YAMAHA SPARK, 135cc	Chassis No:	5YP703324
Reg. Date:	12/12/2005 (Man. Year: 2005)	Odometer:	42164 km
Colour:	Red		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80-17	Rear Tyre Size:	80/90-17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,872.00	3,350.80	521.20	13.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	340.00	260.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,472.00	3,690.80	781.20	17.47
Approved Total (Overridden) (S\$)		2,950.00		
Nett Amount (S\$)	4,472.00	2,950.00	1,522.00	34.03
+ Loss of Use (3.0 x S\$25.00/day) (S\$)		75.00		
Nett Liability (S\$)		3,025.00		

INSPECTION

Date of Assignment:	01/09/2022	
Date Inspected:	01/09/2022	Inspected At: Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06 Singapore 159762
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLER BAR	Bent	85.00 F	*85.00 FL
2	1		*HANDLER BRACKET	Bent	45.00 F	*45.00 FL
3	1		*HANDLER END	Missing	35.00 F	*35.00 FL
4	1		*COWLING STAY	Bent	48.00 F	*48.00 FL
5	1		*UNDER BRACKET	Bent	185.00 F	*185.00 FL
6	1		*STEERING CON	Necessary	98.00 F	*98.00 FL
7	1		*FORK ASST	Bent	480.00 F	*450.00 FL
8	1		*F WHEEL RIM	Bent	380.00 F	*350.00 FL
9	1		*F BRAKE DISC	Bent	180.00 F	*150.00 FL
10	1		*F FENDER	Cut	95.00 F	*80.00 FL
11	1		*F WHEEL SHAFT	Bent	45.00 F	*45.00 FL
12	2		*SIGNAL LIGHT	Missing	98.00 F	*98.00 FL
13	1		*CLUTCH LEVER	Broken	25.00 F	*25.00 FL
14	1		*HEAD LIGHT ASSY	Cut	135.00 F	*135.00 FL
15	1		*RADIATOR ASST	Bent	280.00 F	*280.00 FL
16	1		*HEA LIGHT COVER	Cut	85.00 F	*85.00 FL
17	1		*F COWLING	Broken	165.00 F	*165.00 FL
18	1		*L/H LEG SHIELD	Broken	85.00 F	*85.00 FL
19	1		*R/H LEG SHIELD	Broken	85.00 F	*85.00 FL
20	1		*L/H GUIDER AIR	Cut	45.00 F	*45.00 FL
21	1		*R/H GUIDER AIR	Cut	45.00 F	*45.00 FL
22	1		*CENTER PANEL	Broken	120.00 F	*120.00 FL
23	1		*F FOOT REST BAR	Bent	85.00 F	*85.00 FL
24	1		*F FOOT REST RUBBER	Torn	25.00 F	*25.00 FL
25	1		*BRAKE PEDAL	Bent	68.00 F	*68.00 FL
26	1		*COOLANT	Necessary	35.00 FS	*20.00 FS
27	1		*REAR BOX	Damaged	385.00 FS	*350.00 FS
28	1		*BOX BRACKET	Necessary	185.00 FS	*150.00 FS
29	1		*IU UNIT	Cut	165.00 FS	*165.00 FS
30	1		*IU BRACKET	Not Necessary	35.00 FS	*- FS
31	1		*MIRROR	Broken	45.00 F	*45.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,872.00	3,647.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	296.20
Total Parts (S\$)	3,872.00	3,350.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	100.00	60.00
2	LABOUR	New	500.00	280.00
Gross Labour Cost (\$\$)			600.00	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >