

Cheng Hoe Motor Pte Ltd

Bld 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP AIG
 Claim Type: Third Party
 Accident Date: 29/08/2022
 TP Veh Reg No: SKT14A

*Not withstanding
 1/1 Pump & 2500/-
 Resurvey After Paint
 4 days*

Estimate No: ES2290889/YISHUN
 Date: 30 Aug 2022
 Policy No:
 Veh Reg No: SGQ9438P
 Make/Model: HONDA HONDA HRV
 1.5 DX CVT
 Chassis No: JHMRU1810GX200342
 Engine No:
 Reg. Date: 20/10/2016

Estimate Repair Cost to Vehicle No :SGQ9438P

| Description | U/Price | Quantity | List Price | Amount |
|--|---------|----------|-----------------------------|--------------------|
| | | | SS | SS |
| List Price | | | | |
| 1 REAR TAILGATE | 997.60 | 1 PC | <i>By</i> 997.60 | ✓ |
| 2 TAILGATE EMBLEM - HR-V | 27.00 | 1 PC | <i>Mr</i> 27.00 | ✓ |
| 3 TAILGATE EMBLEM - i-VTEC | 16.70 | 1 PC | <i>Mr</i> 16.70 | ✓ |
| 4 REAR BUMPER | 829.60 | 1 PC | <i>Buy New</i> 829.60 | ✓ |
| 5 REAR BUMPER SIDE PAD LH | 165.70 | 1 PC | <i>Buy</i> 165.70 | ✓ |
| 6 REAR BUMPER SIDE PAD RH | 165.70 | 1 PC | <i>Buy</i> 165.70 | X |
| 7 REAR BUMPER CLIP | 3.90 | 6 PCS | <i>Mr</i> 23.40 | ✓ |
| <i>Smart Key Sensor @84.30 ✓ CM</i> | | | 2,225.70 | |
| | | Less 20% | 445.14 | 1,780.56 |
| Special Net | | | | |
| 8 REVERSE SENSOR | 200.00 | 1 PC | <i>Short</i> 200.00 | ✓ |
| 9 REAR NUMBER PLATE | 35.00 | 1 PC | <i>nd</i> 35.00 | ✓ |
| 10 REAR WINDSCREEN GLASS SEALANT | 40.00 | 1 PC | <i>Mr</i> 40.00 | ✓ |
| | | | 275.00 | 275.00 |
| Labour | | | | |
| 11 REMOVE AND REFIX REAR WINDSCREEN GLASS | 120.00 | 1 LA | 120.00 | ✓ |
| 12 TO PANEL BEATING | 600.00 | 1 LA | 600.00 | 450/- |
| 13 TO PUTTY AND RESPRAY PAINTING | 600.00 | 1 LA | 600.00 | 500/- |
| 14 TO REMOVE AND REFIX REVERSE CAMERA , SENSOR | 40.00 | 1 LA | 40.00 | ✓ |
| 15 RUSTPROOFING | 30.00 | 1 LA | 30.00 | ✓ |
| | | | 1,390.00 | 1,390.00 |
| | | | Total | SS 3,445.56 |
| | | | Add GST @ 7% | 241.19 |
| | | | Total Amount Payable | SS 3,686.75 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE