

来發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

TAX INVOICE

EST No.: EST0030164
 Chew Siew Lian Corine

GST Reg No: M2-0128609-3
 Page: 1 of 4
 Number: INV0033082
 Your ref.: TP-GBH 4540R Lonpac
 Job No.: 72977
 Our ref: 22.08.42
 Payment:
 Date: 25/7/2023

Attn

Vehicle No: SLN 6067C
 Vehicle Model : Mercedes Benz C180
 Accident on ...: 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts-Nett items:					
1.00	Pc	Front bumper	1,790.00	10.00	1,611.00
1.00	Pc	Front bumper LH inner part	108.00	10.00	97.20
1.00	Pc	Front bumper lower inner part	185.00	10.00	166.50
1.00	Pc	Front bumper reinforcement	510.00	10.00	459.00
1.00	Pc	Front bumper sponge	210.00	10.00	189.00
1.00	Pc	Front bumper upper bracket	275.00	10.00	247.50
1.00	Pc	Front bumper chrome moulding	240.00	10.00	216.00
1.00	Pc	Front bumper upper support beam	275.00	10.00	247.50
18.00	Pcs	Front bumper tri-grip rivets	9.00	10.00	145.80
1.00	Pc	Front bumper reinforcement bracket LH	235.00	10.00	211.50
1.00	Pc	Front bumper reinforcement side bracket LH	95.00	10.00	85.50
1.00	Pc	Front support panel	745.00	10.00	670.50
1.00	Pc	Front number plate base	167.00	10.00	150.30
1.00	Pc	Front radiator grille	155.00	10.00	139.50
1.00	Pc	Front radiator grille logo emblem	155.00	10.00	139.50
1.00	Pc	Front seat belt LH	800.00	10.00	720.00
1.00	Pc	Front seat belt RH	800.00	10.00	720.00
1.00	Pc	Front seat belt LH upper trim	103.00	10.00	92.70
1.00	Pc	Headlamp LH	3,617.00	10.00	3,255.30
1.00	Pc	Headlamp RH	3,617.00	10.00	3,255.30

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

TAX INVOICE

EST No.: EST0030164
 Chew Siew Lian Corine

GST Reg No: M2-0128609-3
 Page: 2 of 4
 Number: INV0033082
 Your ref.: TP-GBH 4540R Lonpac
 Job No.: 72977
 Our ref: 22.08.42
 Payment:
 Date: 25/7/2023

Attn

Vehicle No: SLN 6067C
 Vehicle Model : Mercedes Benz C180
 Accident on ...: 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Rear seat belt LH	470.00	10.00	423.00
1.00	Pc	Rear seat belt RH	470.00	10.00	423.00
1.00	Pc	Rear bumper	1,890.50	10.00	1,701.45
1.00	Pc	Rear bumper lower trim	275.00	10.00	247.50
1.00	Pc	Rear bumper chrome moulding	315.00	10.00	283.50
1.00	Pc	Rear bumper lower frame	48.00	10.00	43.20
1.00	Pc	Rear bumper tow hook cover	72.00	10.00	64.80
1.00	Pc	Rear bumper reinforcement	772.90	10.00	695.61
1.00	Pc	Rear bumper lower covering RH	55.00	10.00	49.50
1.00	Pc	Rear bumper lower bracket LH	45.00	10.00	40.50
1.00	Pc	Rear bumper lower bracket RH	45.00	10.00	40.50
1.00	Pc	Rear bumper upper bracket LH	45.00	10.00	40.50
1.00	Pc	Rear bumper upper bracket RH	75.00	10.00	67.50
18.00	Pcs	Rear bumper tri-grip rivets	9.00	10.00	145.80
1.00	Pc	Rear boot lid	2,522.70	10.00	2,270.43
1.00	Pc	Rear boot lid C180 emblem	130.00	10.00	117.00
1.00	Pc	Rear boot lid Mercedes logo emblem	55.00	10.00	49.50
1.00	Pc	Rear boot lid chrome moulding	170.00	10.00	153.00
1.00	Pc	Rear boot lid hinge RH	262.00	10.00	235.80
1.00	Pc	Rear boot lid side covering	55.00	10.00	49.50
1.00	Pc	Rear boot lid striker	565.00	10.00	508.50
1.00	Pc	Rear boot lid lock	325.00	10.00	292.50
1.00	Pc	Rear parking sensor inner RH	210.00	10.00	189.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

TAX INVOICE

EST No.: EST0030164
 Chew Siew Lian Corine

GST Reg No: M2-0128609-3
 Page: 3 of 4
 Number: INV0033082
 Your ref.: TP-GBH 4540R Lonpac
 Job No.: 72977
 Our ref: 22.08.42
 Payment:
 Date: 25/7/2023

Attn

Vehicle No: SLN 6067C
 Vehicle Model : Mercedes Benz C180
 Accident on ...: 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Rear taillamp RH	812.60	10.00	731.34
1.00	Pc	Rear taillamp panel RH	185.00	10.00	166.50
1.00	Pc	Rear end panel	1,655.70	10.00	1,490.13
1.00	Pc	Rear end panel trim garnish	180.00	10.00	162.00
1.00	Pc	Rear fender RH	2,430.00	10.00	2,187.00
1.00	Pc	Rear spare tyre (plastic)	586.50	10.00	527.85
Special nett item:					
1.00	Pc	Front number plate	40.00		40.00
1.00	Pc	Rear spare tyre sealant	40.00		40.00
1.00	Pc	Rear windscreen inner seal	30.00		30.00
Labour & Misc:					
1.00		To reprogram rear boot lid striker	350.00		350.00
1.00		To reprogram SRS collision prevention assist	350.00		350.00
1.00		To dismantle+refix rear cushion seats assy, rear speakerboard, etc	220.00		220.00
1.00		To check/clear fault codes after repair	120.00		120.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

TAX INVOICE

EST No.: EST0030164
Chew Siew Lian Corine

GST Reg No: M2-0128609-3
Page: 4 of 4
Number: INV0033082
Your ref.: TP-GBH 4540R Lonpac
Job No.: 72977
Our ref: 22.08.42
Payment:
Date: 25/7/2023

Attn

Vehicle No: SLN 6067C
Vehicle Model : Mercedes Benz C180
Accident on ...: 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To dismantle+renew front bumper and parts	700.00		700.00
1.00		To straighten rear body including cutting and welding, to knock dents on rear taillamp panel LH, rear floor panel and renew of parts	1,500.00		1,500.00
1.00		To spray paint (front portion)	500.00		500.00
1.00		To spray paint (rear portion/including blending roof panel RH)	1,500.00		1,500.00

Sub-Total 31,566.01
GST 8.00% 2,525.28
Total S\$ 34,091.29

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."