



# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0030164  
Chew Siew Lian Corine

Page .....: 1 of 4  
Your ref. ....: TP-GBH 4540R Lonpac  
Job No. ....: 72977  
Our ref. ....: 22.08.42  
Payment .....  
Date .....: 30/8/2022

Attn .....

Vehicle No ....: SLN 6067C  
Vehicle Model : Mercedes Benz C180  
Accident on ...: 26/8/2022

*NOT Authorised*  
*Running B&P sim*  
*21 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front bumper <i>1790</i>	1,790.00	10.00	<i>Per</i> 1,611.00 ✓
1.00	Pc	Front bumper centre inner part	115.00	10.00	<i>Sim</i> 103.50 ✓
1.00	Pc	Front bumper LH inner part	108.00	10.00	<i>CM</i> 97.20 ✓
1.00	Pc	Front bumper lower inner part	185.00	10.00	<i>CM</i> 166.50 ✓
1.00	Pc	Front bumper reinforcement	510.00	10.00	<i>B</i> 459.00 ✓
1.00	Pc	Front bumper sponge	210.00	10.00	<i>CM</i> 189.00 ✓
1.00	Pc	Front bumper upper bracket	275.00	10.00	<i>B</i> 247.50 ✓
1.00	Pc	Front bumper chrome moulding	240.00	10.00	<i>nd</i> 216.00 ✓
1.00	Pc	Front bumper upper support beam	275.00	10.00	<i>CM</i> 247.50 ✓
18.00	Pcs	Front bumper tri-grip rivets	9.00	10.00	<i>nd</i> 145.80 ✓
1.00	Pc	Front number plate base	167.00	10.00	<i>nd</i> 150.30 ✓
1.00	Pc	Front radiator grille	155.00	10.00	<i>Per</i> 139.50 ✓
1.00	Pc	Front radiator grille logo emblem	155.00	10.00	<i>nd</i> 139.50 ✓
1.00	Pc	Front seat belt LH <i>for</i>	800.00	10.00	<i>Jm</i> 720.00 ✓
1.00	Pc	Front seat belt RH <i>for</i>	800.00	10.00	<i>Jm</i> 720.00 ✓
1.00	Pc	Front seat belt LH upper trim	103.00	10.00	<i>W</i> 92.70 ✓
1.00	Pc	Rear seat belt LH	470.00	10.00	<i>Jm</i> 423.00 ✓
1.00	Pc	Rear seat belt RH	470.00	10.00	<i>Jm</i> 423.00 ✓

6422

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。  
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0030164  
Chew Siew Lian Corine

Page .....: 2 of 4  
Your ref. ....: TP-GBH 4540R Lonpac  
Job No. ....: 72977  
Our ref .....: 22.08.42  
Payment .....  
Date .....: 30/8/2022

Attn .....

Vehicle No ....: SLN 6067C  
Vehicle Model : Mercedes Benz C180  
Accident on ...: 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Rear bumper	2,020.00	10.00	1,818.00
1.00	Pc	Rear bumper lower trim	275.00	10.00	247.50
1.00	Pc	Rear bumper chrome moulding	315.00	10.00	283.50
1.00	Pc	Rear bumper lower frame	48.00	10.00	43.20
1.00	Pc	Rear bumper tow hook cover	72.00	10.00	64.80
1.00	Pc	Rear bumper reinforcement	830.00	10.00	747.00
1.00	Pc	Rear bumper lower covering RH	55.00	10.00	49.50
1.00	Pc	Rear bumper lower bracket LH	117.00	10.00	105.30
1.00	Pc	Rear bumper lower bracket RH	45.00	10.00	40.50
1.00	Pc	Rear bumper upper bracket LH	45.00	10.00	40.50
1.00	Pc	Rear bumper upper bracket RH	75.00	10.00	67.50
18.00	Pcs	Rear bumper tri-grip rivets	9.00	10.00	145.80
1.00	Pc	Rear boot lid	2,700.00	10.00	2,430.00
1.00	Pc	Rear boot lid C180 emblem	130.00	10.00	117.00
1.00	Pc	Rear boot lid Mercedes logo emblem	55.00	10.00	49.50
1.00	Pc	Rear boot lid chrome moulding	170.00	10.00	153.00
1.00	Pc	Rear boot lid hinge RH	290.00	10.00	261.00
1.00	Pc	Rear boot lid side covering	55.00	10.00	49.50
1.00	Pc	Rear parking sensor inner RH	210.00	10.00	189.00
1.00	Pc	Rear tail lamp RH	870.00	10.00	783.00

7864.70

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0030164  
Chew Siew Lian Corine

Page .....: 3 of 4  
Your ref. ....: TP-GBH 4540R Lonpac  
Job No. ....: 72977  
Our ref. ....: 22.08.42  
Payment .....  
Date .....: 30/8/2022

Attn .....

Vehicle No ....: SLN 6067C  
Vehicle Model : Mercedes Benz C180  
Accident on ...: 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00	Pc	Rear tail lamp panel RH	185.00	10.00	166.50	✓
1.00	Pc	Rear end panel <i>1655.70</i>	1,770.00	10.00	1,593.00	✓
1.00	Pc	Rear end panel trim garnish	180.00	10.00	162.00	✓
1.00	Pc	Rear fender RH <i>2430</i>	2,785.00	10.00	2,506.50	✓
1.00	Pc	Rear spare tyre (plastic) <i>586.50</i>	630.00	10.00	567.00	✓
1.00	Pc	Rear windscreen	1,195.00	10.00	1,075.50	X
Special nett item:						
1.00	Pc	Front number plate	40.00		40.00	✓
1.00	Pc	Rear spare tyre panel sealant	40.00		40.00	✓
1.00	Pc	Rear windscreen inner seal	30.00		30.00	✓
1.00	Pc	Rear windscreen solar film + installation	350.00		350.00	X
Labour & Misc:						
1.00		To dismantle + renew rear windscreen	180.00		180.00	X
1.00		To supply windscreen sealant	40.00		40.00	X

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。此外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

**来發 (明記) 摩哆有限公司**  
**LAI HUAT (MENG KEE) MOTOR PTE LTD**

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
 GST No: M2-0128609-3  
 UEN: 199407592C

**ESTIMATE**

EST. No ..... EST0030164  
 Chew Siew Lian Corine

Page ..... 4 of 4  
 Your ref. .... TP-GBH 4540R Lonpac  
 Job No. .... 72977  
 Our ref ..... 22.08.42  
 Payment .....  
 Date ..... 30/8/2022

Attn .....

Vehicle No ... : SLN 6067C  
 Vehicle Model : Mercedes Benz C180  
 Accident on ... : 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To dismantle + refix rear cushion seats assy, rear speakerboard, etc	280.00		280.00 <i>220</i>
1.00		To check/clear fault codes after repair	120.00		120.00 ✓
1.00		To dismantle + renew front bumper and parts	350.00		350.00 <i>300</i>
1.00		To straighten rear body including cutting and welding, to knock dents on rear tail lamp panel LH, rear floor panel and renew of parts	2,000.00		2,000.00 <i>1500</i>
1.00		To spray paint (front portion/including bonnet)	600.00		600.00 <i>500</i>
1.00		To spray paint (rear portion/including blending roof panel RH)	1,800.00		1,800.00 <i>1500</i>

Sub-Total 25,888.30  
 GST 7.00% 1,812.18  
 Total S\$ 27,700.48

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

**来發 (明記) 摩哆有限公司**  
**LAI HUAT (MENG KEE) MOTOR PTE LTD**

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
 GST No: M2-0128609-3  
 UEN: 199407592C

**SUPPLEMENTARY (1) ESTIMATE**

EST. No .....: EST0030164  
 Chew Siew Lian Corine

Page .....: 1 of 1  
 Your ref. ....: TP-GBH 4540R Lonpac  
 Job No. ....: 72977  
 Our ref .....: 22.08.42  
 Payment .....  
 Date .....: 30/9/2022

Attn .....

Vehicle No ...: SLN 6067C  
 Vehicle Model: Mercedes Benz C180  
 Accident on ...: 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
SUPPLEMENTARY ITEM:					
1.00	Pc	Rear boot lid striker	565.00	10.00	<i>R</i> 508.50 ✓
1.00	Pc	Headlamp LH <i>3617</i>	<i>MGM</i> 3,680.00	10.00	3,312.00 ✓
1.00	Pc	Headlamp RH <i>3617</i>	<i>"</i> 3,680.00	10.00	3,312.00 ✓
1.00	Pc	Front bumper reinforcement bracket LH	<i>R</i> 235.00	10.00	211.50 ✓
1.00	Pc	Front bumper reinforcement side bracket LH	<i>CM</i> 95.00	10.00	85.50 ✓
1.00	Pc	Front support panel <i>745</i>	<i>Bu</i> 910.00	10.00	819.00 ✓
Labour & Misc:					
1.00		To dismantle + renew above parts	450.00		450.00 <i>400</i>

*884*  
 Sub-Total 8,698.50  
 GST 7.00% 608.90  
 Total S\$ 9,307.40

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司  
**LAI HUAT (MENG KEE) MOTOR PTE LTD**

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
 GST No: M2-0128609-3  
 UEN: 199407592C

**SUPPLEMENTARY (2) ESTIMATE**

EST. No : EST0030164  
 Chew Siew Lian Corine

Page : 1 of 1  
 Your ref. : TP-GBH 4540R Lonpac  
 Job No. : 72977  
 Our ref. : 22.08.42  
 Payment :  
 Date : 27/10/2022

Attn :

Vehicle No : SLN 6067C  
 Vehicle Model : Mercedes Benz C180  
 Accident on : 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
SUPPLEMENTARY ITEM:					
1.00		To reprogram rear boot lid (Auto)	350.00		350.00 ✓
1.00		To reprogram SRS collision prevention assist	350.00		350.00 ✓

Sub-Total 700.00  
 GST 7.00% 49.00  
 Total S\$ 749.00

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理  
 除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support  
 dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO  
 Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司  
**LAI HUAT (MENG KEE) MOTOR PTE LTD**

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
 GST No: M2-0128609-3  
 UEN: 199407592C

**SUPPLEMENTARY (3)**

**ESTIMATE**

EST. No ..... EST0030164  
 Chew Siew Lian Corine

Page ..... 1 of 1  
 Your ref. .... TP-GBH 4540R Lonpac  
 Job No. .... 72977  
 Our ref. .... 22.08.42  
 Payment .....  
 Date ..... 21/11/2022

Attn .....

Vehicle No .... SLN 6067C  
 Vehicle Model : Mercedes Benz C180  
 Accident on ... 26/8/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Supply of Parts - Nett item:			
		SUPPLEMENTARY ITEM:			
1.00		Rear boot lid lock	<i>Old</i> 325.00	10.00	292.50

Sub-Total 292.50  
 GST 7.00% 20.48  
 Total S\$ 312.98

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."