

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

TO	: AXA <i>Xiao Tong</i>	DATE	: 29.08.2022
ATTENTION	: MOTOR CLAIMS DEPT		
DATE/TIME OF ACCIDENT	: 29.08.2022/0744		
NUMBER PLATE	: SKD5151M	MODEL	: POLO
DATE OF REG	: 16.11.2017		
CHASSIS	: WWWZZZ6RZHU100912		<i>WVWZZZ6RZHU100912</i>

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BONNET	1	\$1,398.90	\$ 1,398.90	+
2	BONNET INNERLOCK <i>from</i>	1	\$165.90	\$ 165.90	+
3	BONNET LOCK CATCH	1	\$35.80	\$ 35.80	+
4	FRONT BUMPER <i>Debond</i>	1	\$1,485.20	\$ 1,485.20	1185
5	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$298.50	\$ 298.50	+
6	FRONT BUMPER REINFORCEMENT <i>New</i>	1	\$785.20	\$ 785.20	+
7	FRONT BUMPER SIDE RETAINER <i>new</i>	1	\$98.60	\$ 98.60	+
8	FRONT BUMPER FOG LAMP COVER <i>crackd</i>	1	\$389.70	\$ 389.70	125
9	FRONT FOG LAMP COVER CHROME <i>new</i>	1	\$145.30	\$ 145.30	+
10	FRONT BUMPER FOG LAMP <i>crackd</i>	1	\$468.70	\$ 468.70	305
11	FRONT BUMPER LOWER BEAM <i>new</i>	1	\$145.90	\$ 145.90	+
12	FRONT BUMPER UNDER COVER GARNISH <i>new</i>	1	\$384.00	\$ 384.00	+
13	FRONT BUMPER WASHER COVER <i>new</i>	1	\$68.90	\$ 68.90	+
14	FRONT BUMPER WASHER NOZZLE <i>new</i>	1	\$198.50	\$ 198.50	+
15	FRONT GRILLE <i>new</i>	1	\$825.60	\$ 825.60	+
16	HEADLAMP <i>cat</i>	1	\$2,345.80	\$ 2,345.80	+
17	HEADLAMP LOWER BRACKET <i>crackd</i>	1	\$388.75	\$ 388.75	75
18	FRONT SUPPORT PANEL <i>crackd</i>	1	\$1,078.90	\$ 1,078.90	880
19	FRONT FENDER LH <i>Distorted</i>	1	\$925.80	\$ 925.80	650
20	FRONT FENDER INNER COWLING LH <i>Debond</i>	1	\$192.30	\$ 192.30	+
21	SIDE MIRROR LH <i>new</i>	1	\$897.50	\$ 897.50	+
22	FRONT DOOR LH <i>Repair</i>	1	\$1,876.90	\$ 1,876.90	+
23	FRONT DOOR HINGES LH <i>new</i>	2	\$125.60	\$ 251.20	+
24	FRONT DOOR CHECKER LH <i>new</i>	1	\$106.80	\$ 106.80	+

25	SIDSKIRT LH <i>Neu</i>	1	\$987.50	\$ 987.50	X
26	FRONT RIM LH <i>ut</i>	1	\$1,325.90	\$ 1,325.90	750/3W
27	FRONT KNUCKLE ARM LH <i>Reid</i>	1	\$977.80	\$ 977.80	645
28	FRONT LOWER ARM LH <i>Best</i>	1	\$699.80	\$ <u>699.80</u>	366
29	FRONT STEERING RACK AND PINION <i>Broken</i>	1	\$4,026.93	\$ <u>4,026.93</u>	2785
30	FRONT DRIVESHAFT LH <i>Neu</i>	1	\$2,291.50	\$ 2,291.50	+
31	FRONT WHEEL HUB BEARING LH <i>Reid</i>	1	\$708.60	\$ <u>708.60</u>	455
32	FRONT ABSORBER LH <i>Best</i>	1	\$425.70	\$ 425.70	✓
33	FRONT STABILIZER LINKAGE <i>Neu</i>	1	\$228.60	\$ 228.60	+
34	FRONT STABILIZER BAR <i>Neu</i>	1	\$987.20	\$ 987.20	+

10533.40
9480.06
S.N: 750

SUBTOTAL PRICE \$ 26,812.73
LESS 10% \$ 2,681.27
TOTAL PRICE \$ 24,131.46

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
2	FRONT BUMPER CLIPS <i>Neu</i>	1 SET	\$ 30.00	\$ 30.00	✓
3	FRONT FENDER COWLING CLIPS <i>Neu</i>	1 SET	\$ 30.00	\$ 30.00	✓
4	FRONT TYRE <i>Neu</i>	1	\$ 380.00	\$ 380.00	+
5	FRONT GRILLE CLIPS <i>Neu</i>	1	\$ 280.00	\$ 280.00	+

60

TOTAL \$ 770.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,600.00	800.	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,600.00	600	
3	Tuff Coat	\$180.00	60	
4	WIRING CHECK ON HEADLAMP & FOCUSING	\$120.00	30	
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$120.00	60	
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$120.00	60	
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE	\$380.00	220	
8	COMPUTERISED WHEEL ALIGNMENT	\$120.00	80.	
TOTAL		\$4,240.00		

TOTAL PARTS COST : \$ 24,901.46
 TOTAL LABOUR COST : \$ 4,240.00
TOTAL REPAIR COST : \$ 29,141.46

1510

Adrian G
 H/S 30/08/22.
 07 Days.
 total: 12200.06
 H/S: 9.71K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: