

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MINISTRY OF DEF	ENCE	Ref:	CC2/MIDA22008453/Apq2	
	HQ TRANSPORT (KRANJI CAMP 3		Date:	03/01/2023	
	151 CHOA CHU KA	ANG WAYSINGAPORE 688248	Code:	MIDA	
1.		Policy Particulars	:- THIRD PARTY CLAIN		
1.	Insured Veh.	MID 21522	Veh. Inspected	SGJ 8954J	
	Policy No.	OA22019968	Coverage (\$)	0.00	
	Claim No.	CY22/MID21522/290822/0032	Excess (\$)	0.00	
	Assign From	O I ZZ/WIIDZ TOZZ/ZOOOZZ/OOOZ	Assign Date	31/08/2022	
2.					
۷.	Make & Model	TOYOTA ALTIS	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	MR053REH104547839	Colour	BLUE	
	Odometer	87291 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	ALTIMEX	6 mm	
	L/H Front Tyre	205/55 R16	ALTIMEX	6 mm	
	R/H Rear Tyre	205/55 R16	ALTIMEX	6 mm	
	L/H Rear Tyre	205/55 R16	ALTIMEX	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	29/08/2022	Inspection Date	31/08/2022	
	Survey held at	at AUTOBACS CAR CARE (S) PTE LTD			
		8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				