

ASS. REC. BY:

REF:

ASm/ 22008458/Kc

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. 1/24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11

1/ Pump @ 5150L Carlow

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

F. 100%

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

AT AUTO CONSULTANT

11k 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No.: 53368526E

Date of Estimate: 29.08.2022
Vehicle No: SMP72D
Owner: PEK SAY ANN
Date of Accident: 26.08.2022
Make & Model: MERCEDES-BENZ E200 R18
Chassis No : WDD2120342B061838

Not Authorized
61 Pay @ 5150/h
Penny After Rain
Today

ESTIMATE FOR ACCIDENT VEHICLE NOS SMP72D

PARTS

1	1	Boot lid			RM	\$2,894.30	X
2	1	Boot lid emblem "MERCEDES"			RM	\$113.10	—
3	1	Boot lid emblem "E200"			RM	\$98.50	—
4	1	Boot lid emblem "7 G-TRONIC"			RM	\$98.50	—
5	1	Boot lid lock			RM	\$638.30	X
6	1	Boot lid weather strip	292		1461N RM	\$456.80	\$506 Jan
7	1	Rear bumper	1405		RM	\$1,972.70	—
8	1	Rear bumper tow cover			RM	\$56.30	—
9	1	Rear bumper lower lid	253.35		RM	\$721.50	—
10	1	Rear bumper lower lid chrome moulding	295.10		RM	\$356.20	—
11	2	Rear exhaust diffuser RH/LH		@	\$895.20	RM	\$1,790.40 X
12	1	Rear bumper inner mounting center			CM	\$265.30	—
13	1	Rear bumper inner bracket center			CM	\$223.50	—
14	2	Rear bumper lower bracket RH/LH		@	\$65.50	CM	\$131.00 —
15	1	Rear reverse sensor wire harness			RM	\$326.80	X
16	1	Rear bumper smart opener bracket			CM	\$335.20	X
17	1	Rear bumper smart opener module			RM	\$752.40	X
18	1	Rear bumper smart opener wiring harness			RM	\$289.10	X
19	1	Rear bumper smart opener sensor top			RM	\$398.50	X
20	1	Rear bumper smart opener sensor lower			RM	\$398.50	X
21	2	Tail lamp RH/LH		@	\$789.50	RM	\$1,579.00 X
22	1	Rear Reinforcement bar	764		RM	\$982.30	—
23	1	End panel			RM	\$785.40	—
24	1	End panel top garnish			CM	\$265.50	—
SUB TOTAL						\$15,929.10	
LESS 10 %						\$1,592.91	
DISCOUNTED SUB TOTAL						\$14,336.19	

S. NETT ITEM

1	4	Reverse sensor original X41	@	\$294.20	\$1,176.80	4
2	6	Rear bumper bracket rivet	@	\$12.50	\$75.00	—
3	1set	Rear bumper clips		RM	\$60.00	—
					\$1,176.80	
					\$0.00	
					\$1,176.80	

LABOUR

1	Panel beating for replace and repair affected parts	1,600.00	600
2	Spray painting on accident areas	1,000.00	600
3	Wiring charges	100.00	200
4	R/R tail boot lid components	350.00	X
5	Apply undercoating to above affected areas	150.00	300
6	Re-programming of rear electronic components	300.00	X
		\$3,500.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 2

Acknowledged by Repairer

Signature:

Date: