

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFF 1520 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	28
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	X
4	TO DISMANTLE AND REINSTALL FRONT BUMPER AND LHS SILL PANEL TRIM. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS A-PILLAR. TO CUT OUT AND WELD LHS A-PILLAR BRACKET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,000.00	1500 + 250 C repair A-pillar bracket
5	TO RESPRAY LHS FRONT FENDER, BONNET, LHS FRONT DOOR, HINGES, LHS WING MIRROR COVER, LHS SILL PANEL TRIM AND LHS A-PILLAR.	\$ 5,500.00	3 x 550 = 1650 Mirror = 150 1800 + 275 C respray A-pillar bracket
6	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	✓
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 14,772.00	

Corin

2/9/22

wp: 39496

* PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Benoit

AIG - Adam

- 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFF 1520 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - LH Distorted	1	\$ 1,560.00	✓
2	FRONT FENDER ATTACHMENT PARTS New	1	\$ 107.00	✓
3	FRONT DOOR STONE CHIP GUARD - LH New	1	\$ 135.00	✓
4	FRONT FENDER BRACE - LH ?	1	\$ 107.00	7 ✓ S.S.
5	FRONT FENDER CLOSING ELEMENT - LH And	1	\$ 60.00	✓
6	FRONT FENDER SEAL STRIP - LH ?	1	\$ 23.00	?
7	FRONT WHEEL HOUSING LINER - LH torn	1	\$ 310.00	✓
8	FRONT WHEEL SPOILER - LH Not in	1	\$ 294.00	✓
9	FRONT WHEEL SPOILER STONE CHIP GUARD - LH New	1	\$ 82.00	+
10	FRONT WHEEL SPOILER ADHESIVE TAPE Green	1	\$ 59.00	+
11	FRONT WHEEL SPOILER TRIM BRACKET - LH	1	\$ 19.00	+
12	WASH WATER RESERVOIR Defect	1	\$ 208.00	✓
13	FUEL FILLER NECK - RH ?	1	\$ 339.00	?
14	WINDSCREEN WASHER SYSTEM PUMP New	1	\$ 138.00	✓
15	CORRUGATED PIPE New	1	\$ 93.00	+
16	PUMP ? And	1	\$ 172.00	✓ S.S.
17	HOSE ?	1	\$ 553.00	?
18	PIPE ? And	1	\$ 45.00	✓ S.S.
19	FRONT DOOR - LH Defect	1	\$ 4,760.00	✓
20	FRONT DOOR STONE GUARD FILM - LH New	1	\$ 135.00	✓
SUB TOTAL SPARE PARTS			\$ 9,199.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.