

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0750/2022/EQ
DATE : 30-Aug-22
WIP : 39496

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. OLIVEIRO GLEN NEVILLE
ADDRESS : 84 RIVERINA VIEW
SINGAPORE 518433
TELEPHONE : HP +65 81234897
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100505829-05
VEHICLE NO : **SFF 1520 G**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 31/3/2017
ENGINE NO : CYG 017684
CHASSIS NO : WAUZZZ4G6HN061552
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Aug-22
PLACE OF ACCIDENT : OUTSIDE 63 RIVERINA CRESCENT 518463,
LOCATION IS JUST AROUND THE CORNER
FROM PLACE OF RESIDENCE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFF 1520 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER LHS FRONT DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 ✓
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	X
4	TO DISMANTLE AND REINSTALL FRONT BUMPER AND LHS SILL PANEL TRIM. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS A-PILLAR. TO CUT OUT AND WELD LHS A-PILLAR BRACKET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,000.00	1500 1750 H/S
5	TO RESPRAY LHS FRONT FENDER, BONNET, LHS FRONT DOOR, HINGES, LHS WING MIRROR COVER, LHS SILL PANEL TRIM AND LHS A-PILLAR.	\$ 5,500.00	2075 3x550 = 1650 Mirror = 150 1800
6	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	✓ X
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 14,772.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFF 1520 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT FENDER - LH <i>Pistola</i>	1	\$ 1,560.00	✓	1248
2	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 107.00	✓	
3	FRONT DOOR STONE CHIP GUARD - LH <i>new</i>	1	\$ 135.00	✓	108
4	FRONT FENDER BRACE - LH <i>new</i>	1	\$ 107.00	7X	
5	FRONT FENDER CLOSING ELEMENT - LH <i>Dmgd.</i>	1	\$ 60.00	7	47.28
6	FRONT FENDER SEAL STRIP - LH <i>new</i>	1	\$ 23.00	7X	
7	FRONT WHEEL HOUSING LINER - LH <i>tom</i>	1	\$ 310.00	✓	248
8	FRONT WHEEL SPOILER - LH <i>new</i>	1	\$ 294.00	✓	
9	FRONT WHEEL SPOILER STONE CHIP GUARD - LH <i>new</i>	1	\$ 82.00	✓	
10	FRONT WHEEL SPOILER ADHESIVE TAPE <i>green</i>	1	\$ 59.00	✓	
11	FRONT WHEEL SPOILER TRIM BRACKET - LH	1	\$ 19.00	✓	
12	WASH WATER RESERVOIR <i>del</i>	1	\$ 208.00	✓	166.40
13	FUEL FILLER NECK - RH <i>new</i>	1	\$ 339.00	7X	
14	WINDSCREEN WASHER SYSTEM PUMP <i>del</i>	1	\$ 138.00	7X	
15	CORRUGATED PIPE <i>new</i>	1	\$ 93.00	✓	
16	PUMP <i>new</i>	1	\$ 172.00	7	137.20
17	HOSE <i>new</i>	1	\$ 553.00	7X	
18	PIPE <i>del</i> damaged	1	\$ 45.00	7	35.92
19	FRONT DOOR - LH <i>del</i>	1	\$ 4,760.00	✓	3808
20	FRONT DOOR STONE GUARD FILM - LH <i>new</i>	1	\$ 135.00	✓	X
SUB TOTAL SPARE PARTS		:	\$	9,199.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFF 1520 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 199.00	+
22	FRONT OUTER DOOR SEAL - LH <i>new</i>	1	\$ 256.00	✓ 204.80
23	BONDING AGENT	1	\$ 51.00	7X
24	CLEANING SOLUTION <i>NP</i>	1	\$ 74.00	7X
25	APPLICATOR <i>new</i>	1	\$ 9.00	7X
26	FRONT DOOR UPPER HINGE - LH <i>new</i>	1	\$ 113.00	+
27	FRONT DOOR UPPER AND LOWER THREADED PLATE - LH / RH <i>new</i>	4	\$ 70.00	+
28	FRONT DOOR LOWER HINGE - LH <i>new</i>	1	\$ 113.00	+
29	FRONT EXTERIOR MIRROR MOUNTING - LH <i>new</i>	1	\$ 1,552.00	+
30	FRONT EXTERIOR MIRROR HOUSING - LH <i>Repis</i>	1	\$ 221.00	+
31	FRONT MIRROR GLASS CARRIER PLATE - LH <i>new</i>	1	\$ 1,298.00	+
32	FRONT TURN SIGNAL INDICATOR - LH <i>new</i>	1	\$ 141.00	+
33	FRONT WINDOW SLOT SEAL TRIM STRIP - LH <i>new</i>	1	\$ 380.00	+
34	ROOF PANEL MOLDING - RH <i>new</i>	1	\$ 571.00	+
35	FRONT WATER DEFLECTOR STRIP - LH <i>new</i>	1	\$ 75.00	+
36	FRONT DOOR WIND - LH <i>lit</i>	1	\$ 1,219.00	✓ 975.20
37	ROCKER MOLDING MOUNT KIT <i>new</i>	1	\$ 93.00	74.24
38	ROCKER MOLDING TAPE <i>new</i>	1	\$ 18.00	14.24
39	FRONT BUMPER STONE GUARD FILM - LH <i>new</i>	1	\$ 133.00	+
40	FRONT FENDER BRACKET - LH <i>new</i>	1	\$ 99.00	7X
SUB TOTAL SPARE PARTS			\$ 6,685.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFF 1520 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	ACRYLIC SEALANT	S/N	\$ 180.00	X
42	CAVITY WAX	S/N	\$ 140.00	X
43	STONE CHIP	S/N	\$ 180.00	X
44	METAL FILLER POWDER	S/N	\$ 280.00	X
45	SUNDRIES		\$ 500.00	? 16-48
TOTAL SPARE PARTS		:	\$ 17,164.00	
TOTAL LABOUR CHARGES		:	\$ 14,772.00	
GRAND TOTAL		:	\$ 31,936.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian
30/08/22

Not Authorised, 06 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0750/2022/EQ

7-Sep-22

Tony

1 of 1

SFF 1520 G

AUDI A6 1.8 TFSI S-TRONIC

Quantity	Description	Unit Price	Amount
Parts			
1	WASHER PUMP SEAL <i>New</i>	\$ 66.00	\$ 52.56 ✓
2	CHANNEL refer Mr. Chang <i>Not New</i>	\$ 717.00	\$ 573.60 ✗
3			
4			
5			
6			
GRAND TOTAL		\$ 783.00	\$ 626.16

For Premium Automobiles Pte Ltd

Authorised Signature