

ASS. REC BY: Toupin REF: CS/ASM 2200.4861 / Aug 3.

ASSIGNMENT


WE 2024 June  
209, June

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated cost: \_\_\_\_\_  
OD / TP / IS / TP RES / OD RES / EVA / INV / MV  
To Inspect/Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: SLV 9989E  
Policy No \_\_\_\_\_  
Claims No S2M049X6  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \$19K  
IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT



Veh No: STR 4986 Yr Regn: 209, June  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Toyota Vios C.C. 1797  
Colour: Blue A/C: Insured / Std / NI / NA  
Sp. Reading: 496272 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: MR053HY9325 / 114287  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 185 / 60R15  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 27/8/2022 D.O.I. 31/8/22  
Survey held at BSL Auto  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/12/22	Lump Sum \$6400 confirmed by email (Red 13,520.75, 67%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 28/12/22-typist

Report Format: TP

Lump Sum / L.B. (\$) \$6400

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

# TSL Auto Garage

Estimate

PAGE : 1/2

YEAR : 2009 VEHICLE NO : SJR4998G  
MODEL : TOYOTA VIOS J AUTO CHASSIS NO : MR053HY9305114281

## Third Party Claims

S/NO	ITEMS	Qty	Price
1	FRONT BUMPER	1	\$790.00 <i>de</i>
2	FRONT BUMPER LOWER GRILLE	1	\$330.00 <i>de</i>
3	FRONT BUMPER TOWING CAP	1	\$96.00 <i>x</i>
4	FRONT BUMPER SIDE RETAINER	2	\$220.00 <i>de</i>
5	FRONT GRILLE	1	\$690.00 <i>de</i>
6	FRONT GRILLE EMBLEM	1	\$85.00 <i>we</i>
7	FRONT FOG LAMP COVER	2	\$220.00 <i>x</i>
8	FRONT BUMPER REINFORCEMENT	1	\$490.00 <i>bt</i>
9	FRONT BUMPER SPONGE	1	\$210.00 <i>de</i>
10	FRONT HEADLAMP	2	\$1,440.00 <i>cu</i>
11	FRONT HEADLAMP LOWER BRACKET	2	\$330.00 <i>x</i>
12	FRONT BONNET	1	\$790.00 <i>x</i>
13	FRONT BONNET HINGE	2	\$220.00 <i>x</i>
14	FRONT BONNET INSULATOR	1	\$210.00 <i>x</i>
15	FRONT BONNET LOCK	1	\$390.00 <i>x</i>
16	FRONT SUPPORT PANEL	1	\$690.00 <i>x</i>
17	FRONT BRACE PANEL	1	\$110.00 <i>bt</i>
18	FRONT AIRCON CONDENSER	1	\$790.00 <i>x</i>
19	FRONT RADIATOR	1	\$820.00 <i>x</i>
20	FRONT RADIATOR SPARE TANK	1	\$220.00 <i>x</i>
21	FRONT FENDER	2	\$770.00 <i>x</i>
22	FRONT FENDER INNER SHIELD	2	\$440.00 <i>x</i>
23	REAR TAILGATE <i>bookid</i>	1	\$890.00 <i>bt</i>
24	REAR TAILGATE HINGE	2	\$330.00 <i>x</i>
25	REAR TAILGATE LOCK	1	\$220.00 <i>bt</i>
26	REAR TAILGATE CENTER CHROME	1	\$190.00 <i>cu</i>
27	REAR TAILGATE EMBLEM "TOYOTA"	1	\$80.00 <i>we</i>
28	WEATHERSHIP	1	\$210.00 <i>cu</i>
29	REAR BUMPER	1	\$710.00 <i>de</i>
30	REAR BUMPER SIDE RETAINER	2	\$220.00 <i>de</i>
31	REAR BUMPER REFLECTOR	2	\$330.00 <i>cu</i>
32	REAR END PANEL	1	\$590.00 <i>bt</i>
33	REAR END PANEL TOP GARNISH	1	\$180.00 <i>de</i>
34	REAR SPARE TYRE PANEL	1	\$810.00 <i>bt</i>
35	REAR SPARE TYRE TOP BOARD	1	\$330.00 <i>cu</i>
36	REAR SPARE TYRE INNER TOOL BOX	1	\$190.00 <i>cu</i>



37	REAR TAIL LAMP	2	\$880.00 <i>one</i>
38	REAR TAIL LAMP LOWER BRACKET	2	\$100.00 <i>X</i>
39	REAR FENDER INNER TRIM	2	\$550.00 <i>X</i>
			\$17,161.00
		Discount 25%	\$4,290.25
		TOTAL :	\$12,870.75

S/NO	SPECIAL ITEMS	Qty	Price
1	FRONT BUMPER CLIPS	1	\$50.00 <i>30 one</i>
2	FRONT FENDER INNER SHIELD CLIPS	2	\$100.00 <i>X</i>
3	FRONT BONNET INSULATOR CLIPS	1	\$50.00 <i>X</i>
4	FRONT GRILLE CLIPS	1	\$50.00 <i>20 one</i>
5	REAR BUMPER CLIPS	1	\$50.00 <i>30 one</i>
6	REAR END PANEL TOP GARNISH CLIPS	1	\$50.00 <i>20 one</i>
7	REAR REVERSE SENSOR	1	\$200.00 <i>one</i>
			\$550.00
		Parts Total :	\$12,870.75
		S/P Item :	\$550.00
		TOTAL :	\$13,420.75

# TSL Auto Garage

Estimate

PAGE : 2/2

YEAR : 2009 VEHICLE NO : SJR4998G  
MODEL : TOYOTA VIOS J AUTO CHASSIS NO : MR053HY9305114281

S/NO	LABOURS	AMOUNT	
1	To straighten and panel beat front and rear frame members, to cut/weld and remove and refit above parts.	\$ 2,600.00	1000
2	To putty, re-spray painting and polish front and rear affected areas.	\$ 2,600.00	1200
3	To rust proof affected areas.	\$ 200.00	50
4	To remove and refit upholstery, seats, garnish, inner trimming boards.	\$ 300.00	60
7	To remove and refit front aircond condenser and refill gas.	\$ 200.00	X
8	To remove and refit front radiator and fill up coolant.	\$ 200.00	X
9	To check and rectify wiring.	\$ 100.00	50
10	To remove and refit rear reverse sensor.	\$ 100.00	30
15	To conduct diagnostic systems and to clear faults code.	\$ 200.00	X

TOTAL : \$ 6,500.00  
PARTS TOTAL : \$ 13,420.75  
GRAND TOTAL : \$ 19,920.75

Tanpin 17495749  
WP' 4/8/22 @ 1030  
L/S Ready after repair  
Tanpin 16 hours on  
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: