

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

LKK Auto Care REG. NO. 201918537M

the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged parts for resurvey

ESTIMATE COST OF REPAIR

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate no. 1148

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FRONT FORK SET X <i>key</i>	\$ 1,800.00		
2	T-INDER BRACKET X	\$ 800.00		
3	STEERING CONE X <i>nn</i>	\$ 250.00		
4	FRONT SPORT RIM X	\$ 450.00		
5	HEAD LAMP <i>cut</i>	\$ 400.00	✓	
6	HEAD LAMP STAY <i>cut</i>	\$ 250.00	X nn	
7	FRONT SIGNAL LIGHT <i>BT</i>	\$ 180.00	90 ✓	
8	HANDLE BAR ? <i>BT</i>	\$ 320.00	250 ✓	
9	HANDLE BAR END <i>mis.</i>	\$ 100.00	50 ✓	
10	HANDLE BRACKET ? <i>X nn</i>	\$ 250.00		
11	HANDLE GRIP X <i>nn</i>	\$ 120.00		
12	BRAKE LEVEL <i>cut</i>	\$ 80.00	✓	
13	SIDE MIRROR <i>cut</i>	\$ 100.00	✓	
14	IU UNIT <i>cut</i>	\$ 155.80	✓	
15	BODY UNDER COVER <i>cut</i>	\$ 280.00	✓	
16	FUEL TANK COVER <i>cut</i>	\$ 280.00	✓	
17	BRAKE PEDAL <i>cut</i>	\$ 220.00	✓	
18	FRONT FOOTREST <i>cut</i>	\$ 150.00	✓	
19	FRONT SIGNAL BRACKET <i>BT</i>	\$ 280.00	✓	
20	LABOUR	\$ 500.00	<i>2ae</i> ✓ 400	

2 Days.

Unpaid Repair

After repair photo

Eno Ri ang - 82880282

Eno Ri ang @ LKK Auto. Com

30/8/2022

Less 10% \$ 696.58

Sub Total : \$ 6,269.22

GST 7% \$ 438.85

Total: \$ 6,708.07

2335.80

-10%

2102.22 + 200

= 2502.22

L/S - 2001.77

= 2000

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.