

CHEONG CHEONG MOTOR SERVICE PTE LTD

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 060/08/2022

Page : 1

Date : 30/08/2022

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01/02
AXA BUILDING
SINGAPORE 068811

Not Withheld
11 Rm & 16,200h
Returning After Rain
12 days

ACCIDENT REPAIR ON : SJV 786 G - MERCEDES E 200
CHASSIS NO :
DATE OF ACCIDENT : 27/08/2022

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

REPLACEMENT OF PARTS

		S\$	S\$
1 BONNET	2551.00	Ry 2,958.50	✓
2 BONNET LOCK		Ort 140.30	2 ✓
3 BONNET UPPER LOCK		R 95.50	X
4 BONNET LOWER LOCK		Ort 126.50	✓
5 BONNET INNER RUBBER		Sm 97.20	X
6 BONNET OUTER RUBBER		Sm 48.80	X
7 BONNET INSULATOR		Pm 208.50	X
8 BONNET HINGE		R 126.50	X
9 FRONT GRILLE		CM 156.40	✓
10 FRONT GRILLE CHROME		CM 315.60	✓
11 FRONT FRILLE EMBLEM		Am 56.40	✓
12 FRONT NUMBER PLATE BASE		Nu 280.60	✓
13 FRONT BUMPER	1280	Bm 1,975.30	✓
14 FRONT BUMPER SIDE RETAINER		2 PCS Sm 178.80	X
15 FRONT BUMPER LOWER CENTRE GRILLE		Sm 135.50	X
16 FRONT BUMPER SPONGE		NJP 255.80	X
17 FRONT BUMPER REINFORCEMENT	605	R 852.20	2 ✓
18 FRONT BUMPER BRACKET		2 PCS R 208.80	X
19 FRONT BUMPER INNER CARRIAGE		Sm 288.80	X
20 FRONT BUMPER PROTECTOR		2 PCS Sm 237.60	X
21 FRONT BUMPER SIDE CHROME		2 PCS R 273.70	✓
22 FRONT BUMPER WIPPER COVER RIGHT		Ort 182.10	✓
23 FRONT BUMPER WIPPER NOZZLE RIGHT		Ort 385.40	✓
24 FRONT BUMPER WIPPER BRACKET RIGHT		CM 208.10	✓
25 FRONT SUPPORT PANEL	640	R 1,204.30	✓
26 FRONT SUPPORT PANEL TOP GARNISH		NJP 180.20	X
27 FRONT SUPPORT PANEL SIDE GARNISH	ols	2 PCS Bm 376.80	✓
28 FRONT BRACE PANEL		R 102.20	✓
29 INNER COOLER ASSY	1280	Pm 1,649.10	✓
30 AIR CONDENSER ASSY	1201.70	Pu 1,565.20	✓
31 RADIATOR ASSY		Pu 1,150.80	✓
32 HEADLAMP	c 1104.00	2 PCS 6,375.60	✓
33 HEADLAMP TOP PANEL	ols Bm	2 PCS 347.30	✓
34 BOOTLID LOCK		R 274.50	X
35 BOOTLID EMBLEM LOGO		R 46.10	✓
36 BOOTLID EMBLEM E200		R 72.80	✓
37 BOOTLID EMBLEM C&C		R 64.20	✓
38 BOOTLID EMBLEM KOMPRESSOR		R 59.20	✓
		23,261.20	



e-mail : c2msvc@singnet.com.sg

Date : 30/08/2022

23,261.20

QTY	DESCRIPTION	UNIT	PRICE	TOTAL
39	BOOTLID WEATHERSTRIP	cm	177.70	3061.20
40	TAILLAMP LEFT	cm	732.30	88.85
41	TAILLAMP SIDE COVER LEFT	cm	242.70	
42	TAILLAMP INNER PANEL LEFT	R	485.40	
43	REAR BUMPER	Bu	1,842.80	
44	REAR BUMPER TOW COVER	mi	76.20	
45	REAR BUMPER SIDE RETAINER	0/1000 2 PCS	134.20	
46	REAR BUMPER DIFFUSER	Pu	328.90	
47	REAR BUMPER REVERSE SENSOR	Shorted 2 4PCS	723.20	361.60
48	REAR BUMPER REVERSE SENSOR HOLDER	2 4PCS Shorted	88.80	44.40
49	REAR BUMPER LOWER RETAINER	2 PCS	84.20	
50	REAR BUMPER PROTECTOR	Pu	398.80	
51	REAR BUMPER CENTRE CHROME	220	268.20	
52	REAR BUMPER SIDE CHROME LEFT	155	190.40	
53	REAR BUMPER SPONGE	mi	246.20	
54	REAR BUMPER BRACKET	2 PCS	206.80	
55	REAR BUMPER INNER CARRIAGE	cm	260.80	
56	REAR BUMPER REINFORCEMENT	775	789.50	
57	REAR END PANEL	955	1,205.80	
58	REAR END PANEL INNER PANEL	205	1,030.80	
59	REAR END PANEL TOP GARNISH	cm	395.60	
60	SPARE TYRE TOP BOARD	cm	579.80	

Date:

30 415 27

61 FRONT NUMBER PLATE
62 FRONT NUMBER PLATE HOLDER

FRONT PORTION :

63	TO REMOVE RENEW & REFIT AIR CONDENSER ASSY TO FACILITATE REPAIR	300.00	100
64	TO REMOVE RENEW & REFIT ALL ACCIDENT DAMAGE PARTS CUT & WELD PANEL BEAT & STRAIGHTEN ALL ACCIDENT AREAS & FIT THE ABOVE SAME	1,000.00	600
65	TO PUTTY & SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS & OTHER ACCIDENT AFFECTED AREAS	1,000.00	660
REAR PORTION :			
66	TO REMOVE RENEW & REFIT ALL ACCIDENT DAMAGE PARTS CUT & WELD PANEL BEAT & STRAIGHTEN ALL ACCIDENT AREAS & FIT THE ABOVE SAME	1,000.00	700
67	TO PUTTY & SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS & OTHER ACCIDENT AFFECTED AREAS	1,000.00	800
68	TO SPARY ANTI RUST ON ACCIDENT PANEL	100.00	90
		34,815.27	

