



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 966P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED/DENTED	2,174.30	2,087.20
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	870.00	-
2	REAR BUMPER SIDE RETAINER UPPER @\$56.20	SERVICEABLE	112.40	-
2	REAR BUMPER SIDE REFLECTOR @\$231.95	O/S CRACKED	463.90	82.00
1	REAR EXHAUST CHROME GARNISH INNER BRACKET O/S	CRACKED	191.25	191.25
1	REAR BUMPER LOWER	DENTED/CUT	669.70	669.70
1	REAR EXHAUST CHROME GARNISH O/S	DENTED	450.00	409.00
1	REAR BUMPER CENTER BRACKET	SERVICEABLE	90.00	-
2	REAR BUMPER SIDE RETAINER LOWER @\$56.20	SERVICEABLE	112.40	-
	LESS 5% DISCOUNT		-256.70	-171.96
			4,877.25	3,267.19
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	294.75	294.75
1	REAR BUMPER SENSOR HOLDER (SN)	NECESSARY	26.00	26.00
12	REAR BUMPER CLIPS @\$5.50 (SN)	NOT NECESSARY	66.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			436.75	320.75
<u>LABOUR</u>				
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		1,200.00	220.00
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS.		50.00	20.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.	NOT NECESSARY	100.00	-

Report Ref No. CS/INC22008477/Kqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL.		1,000.00	250.00
			2,350.00	490.00
GRAND TOTAL			7,664.00	4,077.94
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,077.94

Report Ref No. CS/INC22008477/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.