

車貿易服務

MOTOR TRADING & SERVICE

Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

ur Ref: TP 3085/08/22

Your Ref:

Not Authorised

2/9/22

4/5 \$7000

5 days

MR TOH SWEE KIAN
BLK 853, #11-3515
YISHUN RING RD, S(760853)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost of repair to TOYOTA HIACE SUPER GL BUS - CB 8291 C

1 pc o/s head lamp assy (LED)	SCR	2,832.20	/
1 pc front bumper	cur/7000	586.80	/
1 pc front bumper o/s side bracket	cne	154.20	/
10 pcs front bumper clips	nu	47.00	/
1 pc front o/s step panel	R	100.50	x
1 pc front o/s step panel garnish	dis	175.40	/
6 pcs front o/s step panel garnish clips	nu	28.20	/
1 pc front o/s door	dis/scr	2,038.90	/
2 pcs front o/s door top & low hinge	11	193.00	x
16 pcs front o/s door inner trim board clips	11	76.80	x
1 pc front o/s door pillar panel	R	397.70	x
2 pcs front & rear o/s wheel hupcab	cur	459.40	/
1 pc o/s side door	dis/scr	2,032.90	/
1 pc o/s side door sticker	nu	45.00	/
1 pc o/s side door lower roller bracket	11	360.80	x
1 pc o/s side door glass seal	nu	58.00	/
1 pc o/s side door sealant	11	60.00	/
1 pc o/s side door dam rubber	nu	59.50	/
1 pc rear o/s fender panel	R	1,220.20	x
1 pc rear o/s fender glass seal	11	65.00	x
1 pc rear o/s fender glass dam rubber	11	59.50	x
1 pc rear o/s fender glass sealant	11	60.00	x
1 pc rear bumper	R	466.80	x
1 pc rear bumper o/s side bracket	11	25.30	x
10 pcs rear bumper clips	11	45.00	x
20 pcs o/s side door inner trim board clips	11	96.00	x
1 pc front o/s door weatherstrip	11	283.20	x
1 pc o/s side door weatherstrip	11	359.50	x

25%
Less 20%
\$ 12,386.40
\$ 2,477.28
\$ 9,909.12

To remove & refix o/s side door & rear o/s fender glass. 300.00 120

To remove & refix front o/s door, o/s side door trim board cover, door glass, moulding, lock, glass, regulator, handle & necessary parts. 300.00 100

To check & adjust front & rear o/s wheel alignment & balancing balancing. 11 150.00 X

To remove & refix cushion seat, carpet, floor mat, garnish, safety belt & necessary parts. 180.00 80

\$ 10,839.12

Balance C/F.....

汽車貿易服務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3085/08/22 Your Ref: Date: 30th AUG 2022

MR TOH SWEE KIAN.,

Balance B/F..... \$ 10,839.12

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s wheel panel & necessary parts, to weld, renew & align above parts.

2,400.00 800

To putty & respray painting on all affected accident parts.

2,400.00 1200

To respray Tuff-Kote on all affected accident parts.

120.00 60

To wiring check up for affected wiring system.

60.00 20

To remove & refix for checking front o/s shock absorber shaft, lower arm, wheel bearing & necessary parts.

200.00 X

\$ 16,019.12

Dollars : Sixteen Thousand Ninteen And Cents Twelve Only.

HUP MOTOR TRADING & SERVICE

7-8577.50
252
6433.12
2380
7813.12