

ASS. REC. BY:

REF:

ASM/ 22 0084841ke

Kennerth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

619 84742.85 Carhu 14/9/22

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

CBL 2970A

Yr Regn:

04, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

C.C

15PZ

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

73541

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VM 20 164601

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

29/8/22

D.O.I.

2/9/2022

10am

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorised
Murray B. G. P. M.

84742-65 Sdaps

REPAIR ESTIMATE GBL2970A

Spare Parts

No.	Qty	Nett Items				
1	1	Rear bumper	566.90	clj	\$ Bu	785.90 ✓
2	2	Rear bumper side retainer			\$ Dis	74.40 ✓ 37.20
3	2	Rear bumper reflector			\$ Asp	123.80 X
4	1 set	Rear bumper clips			\$ m	30.00 ✓
5	1	Rear bumper inner foam			\$ cm	103.00 ✓
6	1	RH taillamp			\$ Cu	235.20 ✓
7	1	Rear tailgate	1659		\$ Bt	1,981.20 ✓
8	1	Rear tailgate top centre "NISSAN" logo			\$ m	64.90 ✓
9	1	Rear tailgate LH "NV 200" emblem			\$ m	94.40 ✓
10	1	Rear tailgate LH "VANETTE" emblem			\$ m	87.90 ✓
11	1	Rear tailgate top lock			\$ n	287.10 X
12	1	Rear tailgate weatherstrip			\$ m	97.40 X
13	1 set	Rear tailgate inner trim board clips			\$ m	60.00 X
14	1	Rear end panel outer			\$ Bt	380.00 ✓
15	1	Rear end panel inner			\$ n	690.00 X
16	1	Rear end panel top garnish			\$ m	98.80 X
					\$	5,194.00
				Less 10%	\$	519.40
				Total :	\$	4,674.60

Special Nett Items

17	1	Rear tailgate LH "70km/h" sticker	\$	<i>m</i>	15.00	<i>—</i>
18	1	Rear tailgate RH "6pax" sticker	\$	<i>m</i>	15.00	<i>—</i>
19	1 set	Reverse sensors	\$	<i>Sub</i>	250.00	<i>200.00</i>
20	1 set	Rear end panel sealant	\$	<i>m</i>	50.00	<i>30.00</i>
21	1 set	Rear windscreen sealant	\$	<i>m</i>	50.00	<i>40.00</i>
			Total :	\$	380.00	

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,000.00 600
2	To putty and spray Spray Paintings charges.	\$	1,000.00 600
3	To remove, refit rear tailgate windscreen glass.	\$	140.00 120
4	To check wirings and lightings.	\$	40.00 20
5	To remove, transfer rear tailgate fittings.	\$	80.00 60
6	To replace reverse sensors & reverse camera.	\$	120.00 50
7	To apply anti rust treatment	\$	80.00 60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts and Labour

\$ 7,514.60