



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

not Authorized
all
1/9/22
2/5 @ 5600
6 days.
take photo after repair

2 September 2022

REG NO. : SLX 5363 B
 MAKE/MODEL : KIA CERATO K3

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear windscreen moulding <i>all</i>	\$ 98.60 ✓
1	Rear taillamp - LH <i>1 1</i>	\$ 487.60 X
1	Rear bumper <i>Dis</i>	\$ 658.00 ✓
1	Rear bumper side retainer <i>all surf</i>	\$ 38.50 ✓
1	Rear fender -LH <i>3rd side warped</i>	\$ 889.60 ✓
1	Rear fender air gate <i>1 1</i>	\$ 48.50 X
1	Rear fender inner shield <i>1 1</i>	\$ 58.60 X
1	Rear fuel lid <i>1 1</i>	\$ 135.00 X
<i>2 pcs</i>	Rear wheel hub with bearings <i>@ 280 Dage</i>	\$ 560.00 ✓
1	Rear shock absorber <i>twi</i>	\$ 221.60 ✓
1	Rear axle beam <i>surf/twi</i>	\$ 833.00 ✓
1	Rear door -LH <i>worped</i>	\$ 935.00 ✓
2	Rear door hinges <i>1 1</i>	\$ 116.00 X
1	Rear door inner board <i>1 1</i>	\$ 622.00 X
1	Rear door lock <i>1 1</i>	\$ 300.00 X
1	Rear door outer handle <i>1 1</i>	\$ 65.00 X
1	Rear door regulator with support <i>1 1</i>	\$ 453.00 X
1	Rear door regulator motor <i>1 1</i>	\$ 351.00 X
1	Rear door weatherstrip <i>1 1</i>	\$ 145.00 X
		\$ <u>7016</u>
	Less 10%	\$ <u>6314.40</u>

SPECIAL NETT ITEMS

1	Rear windscreen sealant	ALL	\$	80.00	40
1	Rear bumper clip (1 set)	per	\$	50.00	30
1	Rear fender inner shield clip (1 set)	11	\$	45.00	X
1	Rear tyre	115	\$ 4200	400.00	802120
2pc)	Rear wheel rims @425	cut	\$ 400x2	850.00	800
1	Rear door black tape	115	\$	120.00	50
		per			
			\$	<u>1,545.00</u>	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	180.00	80
3	To remove and refit rear reverse sensor.	\$	120.00	50
4	To remove and refit fuel tank assembly with all attachments.	\$	180.00	60
5	To remove and refit rear undercarriage.	\$	350.00	200
6	To conduct wheel alignment.	\$	180.00	80
7	To remove and refit rear windscreen glass.	\$	180.00	120
8	To apply undercoating.	\$	200.00	60
9	Panel beating.	\$	1,500.00	680
10	To re-spray painting on the affected areas.	\$	1,400.00	800
		\$	<u>4,370.00</u>	

GRAND TOTAL :

\$ 12229.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-4234.3
10%
3810.87
1040
2150
7000.87
212
5600.