

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 16 Sep 2022

**Preliminary Advice**

Vehicle No	: SGR52Y	Accident Date	: 16/08/2022
Make	: TOYOTA VELLFIRE	Policy No.	: SP200743851-01
Assignment Date	: 31/08/2022	Excess	: S\$600.00
Date of Inspection	: 12/09/2022	Est. Duration of Repair	: 4
Inspection At	: CHENG AUTO BODYWORKS (HQ) 5 SOON LEE STREET #01-62 PIONEER POINT SINGAPORE 627607		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,573.00 (estimate \$11,452 + supp \$121)
Revised Amount	:S\$	4,237.00 (inclusive Supp \$121.00)
Check Items (Estimated)	:S\$	5,514.00
Total	:S\$	9,872.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	152,000.00
COE / PARF Rebate	:S\$	59,298.00
Salvage Value	:S\$	
Margin for Repair	:S\$	92,702.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : kindly approve on supplementary.