

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 20 Sep 2022

Preliminary Advice

Insured Vehicle No	: SLN6597P	Accident Date	: 29/08/2022
TP Vehicle No	: SNC5469S	Assignment Date	: 31/08/2022
Make	: VOLKSWAGEN GOLF	Est. Duration of Repair	: 8
Date of Inspection	: 31/8/2022		
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM)		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,402.73
Revised Amount	:S\$	17,288.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	17,288.72
Lump Sum Repair	:S\$	13,800.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	33,204.00
Salvage Value	:S\$	
Margin for Repair	:S\$	56,796.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .