



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22008494/Evy3e2 Date: 07/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 2P	Veh. Inspected	SNG 5988P
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/08/22/2078	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	31/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER	c.c	2487
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	JTEAD3BH40J001204	Colour	BLACK
	Odometer	3813 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	MICHELIN	5 mm
	L/H Front Tyre	225/55 R17	MICHELIN	5 mm
	R/H Rear Tyre	225/55 R17	MICHELIN	5 mm
	L/H Rear Tyre	225/55 R17	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/08/2022	Inspection Date	14/09/2022
	Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	