10/17/22, 12:58 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI22008497/ANY3Q2

Date: 17/10/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle YK3241Y Insured Vehicle No: XB6288C

Date of Loss: 27/08/2022 Nature of Claim: TP Claim No: CDMCG22001819

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YK3241Y

 Make & Model:
 MITSUBISHI FUSO, 3.0 D FE83BE6SRDEA (M)
 Engine No:
 4D34K59963

 Reg. Date:
 03/03/2006 (Man. Year: 2005)
 Chassis No:
 FE83PEA00687

 Colour:
 Silver
 Odometer:
 491702 km

Engine Capacity: 3908 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,005.52	1,784.20	1,221.32	40.64
Miscellaneous Items		0.00	0.00	0.00	
Labour		850.00	520.00	330.00	38.82
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,855.52	2,304.20	1,551.32	40.24
	Approved Total (Overridden) (S\$)		1,800.00		
	(S\$)	3,855.52	1,800.00	2,055.52	53.31
	+ GST 7.00/7.00% (S\$)	269.89	126.00	143.89	53.31
	Nett Amount (S\$)	4,125.41	1,926.00	2,199.41	53.31

INSPECTION

Date Inspected:

Date of Assignment: 31/08/2022

Ryder Auto Pte Ltd (HQ)
28/09/2022 Inspected At: 2 Kaki Bukit Ave 2, #02-19 Auto

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit

Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Oct 2022)

Parts: N/A MITSUBISHI FUSO 3.0 D FE83BE6SRDEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YK3241Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	1,504.30 FL	*1,290.00 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	245.60 FL	*245.60 FL
3	1		*FRONT N/S SIDE MIRROR BRACKET	Bent	485.60 FL	*325.00 FL
4	1		*FRONT N/S SIDE SIDE MIRROR GARNISH ROUND	Cracked	120.00 FL	*50.00 FL
5	1		*FRONT N/S SIDE GARNISH	Cracked	175.00 FL	*95.00 FL
6	1		*FRONT O/S SIGNAL LAMP	Not Necessary	410.20 FL	*- FL
7	1		*FRONT WINDSCREEN SOLAR FILM	Not Necessary	300.00 FS	*- FS
8	1		*FRONT OS DOOR COMPANY STICKER	Necessary	500.00 FS	*280.00 FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)	3,740.70	2,285.60
			- List Item Discount on L Items	25.00/25.00% (S\$)	735.18	501.40
				Total Parts (S\$)	3,005.52	1,784.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO DISMANTLE ,REFIT & REPAIR DAMAGED PARTS	New	200.00	150.00
2	TO SPRAY PAINTING	New	400.00	250.00
3	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	200.00	120.00
4	TO CHECK WIRING	New	50.00	0.00
		Gross Labour Cost (S\$)	850.00	520.00
	Report was unsubm	nitted during this print-out.		

< END OF ESTIMATES >