Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three Singapore 038988

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 13 Oct 2022 Date:

Preliminary Advice

Insured Vehicle No : XB6288C

TP Vehicle No : YK3241Y : 27/08/2022 Accident Date Make : MITSUBISHI FUSO Assignment Date : 31/08/2022

Date of Inspection : 28/09/2022 Est. Duration of Repair : 3

Inspection At : RYDER AUTO PTE LTD (HQ)

2 KAKI BUKIT AVE 2, #02-19 AUTOHUB @ KAKI BUKIT

SINGAPORE 417921

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,296.63
Revised Amount	:S\$	2,304.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,304.20
Lump Sum Repair	:S\$	1,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to (X) consistency check, part prices and labour cost.