

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

FE86PEA00687

ESTIMATE OF REPAIR

Veh# : YK3241Y

Accident Date : 27/8/2022

Location : 74 WOO MON CHEW ROAD

TP Ergo
Hui Ray

Model:

mitsubishi FE83

3/32006-2/3/2026

3P:

XB6288C (ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front windscreen <i>Cracked</i>	1504.30	✓ 1290	
2	1 pc	Front windscreen solar film <i>new</i>		300.00	+
3	1 pc	Front windscreen moulding <i>in</i>	245.60	✓	
4	1 pc	Front n/s side mirror bracket <i>Best</i>	485.60	325	
5	1 pc	Front n/s side side mirror garnish round <i>Cracked</i>	120.00	50	
6	1 pc	Front n/s side garnish <i>Cracked</i>	175.00	95	
7	1 pc	Front o/s signal lamp <i>new</i>	410.20	+	
8	1 pc	Front os door company sticker <i>new</i>		500.00	280
		<i>2005.60 S/N 280</i>	Sub-Total:	2,940.70	800.00
			25%	0%	0%
		<i>1504.20</i>	After Less %:	2,646.63	800.00
		Labour			
1		To dismantle, refit & repair damaged parts		200.00	150
2		To spray painting		400.00	250
3		To remove and repalce front windscreen <i>520</i>		200.00	120
4		To check wiring		50.00	x
		Sub-Total:		850.00	
		Total:		4,296.63	
		After Less 20%:		3,437.30	

Chan San Choon

Director

DipEng, AAE MIMI, MSME (Auto)



LUK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

24 hr accident call

Mobil 1

