



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CS/CTI22008503/Aqy3

Date: 31/08/2022

Code: CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SFX 1115Z	<b>Veh. Inspected</b>	GBH 4025L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM22D206008/C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ALFRED TOH	<b>Assign Date</b>	31/08/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

--	--

### 5. General Information

<b>Accident Date</b>	20/08/2022	<b>Inspection Date</b>	01/09/2022
<b>Survey held at</b>	POWER BUILD TECHNOLOGY ENGINEERING SERVICES 2 Kaki Bukit Avenue 2 #01-36 Kaki Bukit Autohub, Singapore 417921		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--