

POWER BUILD TECHNOLOGY ENGINEERING SERVICES
 BLK 223A #02-213 SERANGOON AVE 4
 SINGAPORE 551223
 TEL:88239929

DATE:29.8.2022

M:PARTNER L21.6AT
 Y: 2018
 C:VF37FBHYMHJ752462
 E:10JBHW3018735
 DOA: 20/8/22

DEAR SIR/ MADAM

TP Chim
 Xiao Chen

ESTIMATED COSTS OF REPAIR FOR GBH4025L

1	REAR DOOR LH <i>Dented</i>	\$1850.00 ✓ 1550
2	REAR DOOR RH <i>Repair</i>	\$1850.00 +
3	REAR DOOR WEATHERSTRIP <i>New</i>	\$345.00 +
4	REAR DOOR LH UPPER HINGE	\$289.00 +
5	REAR DOOR LH LOWER HINGE <i>New</i>	\$289.00 +
6	REAR DOOR INNER TRIM BOARD LH <i>New</i>	\$295.00 +
7	REAR DOOR LH LOCK <i>Repair</i>	\$245.00 —
8	REAR DOOR LH LOCK CATCH <i>New</i>	\$95.00 +
9	REAR DOOR EMBLEM <i>New</i>	\$89.00 ✓
10	REAR NUMBER PLATE <i>Best</i>	\$60.00 → 30(SW)
11	REAR NUMBER PLATE HOLDER <i>Dented</i>	\$80.00 → 30(SW)
12	REAR LH TAILLAMP <i>Best</i>	\$780.00 235
13	REAR NUMBER PLATE LAMP ASSY X 2 @ \$180.00 <i>Repair</i>	\$360.00 120
14	REAR BUMPER ASSY <i>Dented</i>	\$980.00 ✓
15	REAR BUMPER REINFORCEMENT <i>Dented</i>	\$750.00 440
16	REAR BUMPER BRACKET X2 @ \$89.00 <i>New</i>	\$178.00 ✓
17	REAR END PANEL <i>Dented</i>	\$650.00 ✓
18	REAR REVERSE SENSOR <i>Repair</i>	\$350.00 → 200(SW)
19	REAR REVERSE CAMERA <i>Repair</i> Lens 16/1: 403830	\$680.00 → 380(SW)
20	REAR DOOR GLASS SEALANT <i>New</i> S.N: 680	\$100.00 → 40(SW)

LABOUR CHARGES TO DIMANTLE AND REFIX,PANEL BEATING,STRAIGHTENING,REALINGNMENT,REWELD,RECUT TO FACILITATE REPLACEMENT OF REAR DAMAGED PARTS \$1750.00 *SW*

LABOUR CHARGES FOR SPRAY PAINTING ON ALL AFFECTED DAMAGED PORTION AND REPLACEMENT PARTS \$1450.00 *600*

LABOUR CHARGES TO REMOVE AND INSTALL REAR DOOR GLASS \$200.00 *60.*

LABOUR CHARGES FOR CHECKING ALL LIGHTING SYSTEM, REINSTALL REAR REVERSE SENSORS AND RESVERSE CAMERA

~~\$450.00~~ \$0.

LABOUR CHARGES TO APPLY RUST PROOFING CHEMICALS AND BODY SEALANTS TO ALL DAMAGE PARTS

1570

~~\$500.00~~ 60.

TOTAL:

\$14,665.00

Adrian
w/s. 01/09/22.

06 days.

total: 6288.30

w/s : SK.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: