



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS/LPC22008504/Ecy3e2 Date: 09/12/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	YQ 6874U
Policy No.	Z/22/VC00/113342	Coverage (\$)	0.00
Claim No.	22/22/22/VC00/026217	Excess (\$)	600.00
Assign From	GERALD POH	Assign Date	31/08/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA 150	c.c	2755
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	JHHAGV4690K002262	Colour	SILVER
Odometer	9485 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/75 R15	BRIDGESTONE	4 mm
L/H Front Tyre	175/75 R15	BRIDGESTONE	4 mm
R/H Rear Tyre	175/75 R15	BRIDGESTONE	4 mm
L/H Rear Tyre	175/75 R15	BRIDGESTONE	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/08/2022	Inspection Date	31/08/2022
Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
5a. Remarks			
A)THE MARKET VALUE IS S\$99,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	