



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref :	WH1412
Vehicle No. :	YQ6874U
Make & Model :	TOYOTA DYNA 150 5MT

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front Windscreen rubber seal / TN		\$100.00	/
1	Wiper arm rh / BT		\$70.00	/
1	Wiper arm cover rh / MIS		\$10.00	8/
1	Wiper panel / OO		\$140.00	/
1	Front panel / OO		\$450.00	/
1	Front side panel rh / MIS		\$95.00	/
1	Front side panel clips @4*\$3 / MC		\$12.00	/
1	Center grille assy / BR		\$280.00	/
1	Center grille logo badge / M		\$45.00	/
1	Center grille clips @10*\$3 / M		\$30.00	/
1	Headlamp rh / BR		\$290.00	330/
1	Front bumper / BR		\$220.00	/
1	Front bumper fog lamp cover rh / BR		\$60.00	45/
1	Front bumper side bracket rh / BT		\$100.00	/
1	Side mirror rh / CUT		\$75.00	/
1	Front door rh / OO		\$580.00	/
1	Front door lower hinge rh / BT		\$45.00	40/
1	Front door window side garnish rh / CUT		\$50.00	60/
1	Front door weatherstrip / CRM		\$90.00	/
1	Front door lower rubber seal / TN		\$35.00	/
1	Step up garnish / BR		\$120.00	/
1	Step up garnish bracket / BT		\$120.00	/
1	Wheel arch rubber seal Rh / TN		\$25.00	/
1	Wheel arch front mudflap panel rh / OO		\$130.00	/
1	Wheel arch rear mudflap rh / CRM		\$90.00	/
1	Wheel arch rear mudflap lower rubber shield rh / TN		\$90.00	50/
1	Wheel arch rear mudflap bracket rh / BT		\$180.00	/
1	Air cleaner box / BR		\$270.00	490/
1	Brake air vacuum box / OO		\$180.00	/
1	Brake air vacuum box sensor / BR		\$70.00	/
1	Steering rack control box / ? M		\$1,800.00	X

1	Front absorber rh	? / BT	\$70.00	/
1	Front lower arm	? / BT	\$240.00	/
1	Front lower arm ball joint	? / BT	\$75.00	/
1	Front upper arm	? / BT	\$370.00	360 /
1	Front knuckle arm	? / BT	\$240.00	-
1	Rack end rh	/ BT	\$75.00	/
1	Tie rod end Rh	/ BT	\$75.00	70 /
1	Front door pillar RH (Repair refer to labour)		\$0.00	
1	Front floor panel (Repair refer to labour)		\$0.00	
1	A pillar RH (Repair refer to labour)		\$0.00	
			\$6,947.00	
Part Items Total:			15%	\$1,042.05
				\$7,989.05
SPECIAL NETT ITEMS				
1	Front bumper clips	/ AK	\$35.00	
1	Front panel sealant	/ AK	\$60.00	
1	IU Sticker	/ AKC	\$10.00	
SN Items Total:			\$105.00	
Total Parts:			\$8,094.05	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 8773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH1412		Page No. 2	
Vehicle No. : YQ6874U			
Make & Model : TOYOTA DYNA 150 5MT			
S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To remove and replace Front windscreen	100.00	/
5	To remove and replace front undercarriage RH	200.00	/
6	To remove and refit/replace front door RH fitting, trimmings, garnish, window glass and lock mechanism	150.00	50
7	To carried out wheel alignment	80.00	/
Labour Total :		3390.00	
TOTAL (PARTS & LABOUR):		11484.05	

Steve (LKK)
31/8/22, 11.00

OO- L1 11L
EXPERI-?
PIP
by BL y
10 dgs

LKK Auto Consultant hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts provided subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Subject to insurance approval from insurance Company

Acknowledged by Repairer
Signature:
Date:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YQ6874U TOYOTA DYNA 150 SMT

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Front door window top garnish RH / CUT		60.00	/
1	Front door lock RH / BT		120.00	/
1	Front door handle RH / BR		60.00	/
1	Front door regulator RH / BT		90.00	/
1	Front door glass RH / CUT		250.00	/
1	Wiper linkage / BT		140.00	/
1	Front panel emblem "DYNA" / REC		35.00	/
			755.00	
			15%	
			113.25	
			868.25	
<u>SPECIAL NETT ITEMS</u>				
<u>LABOUR</u>				
Total Parts			868.25	