

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLP9996R
TP/Allianz

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01 SINGAPORE 068897

Claim No: ES2290937

Estimate No: ES2290937/YISHUN

Date: 13 Sep 2022

Policy No: 22-MS005805-R03

Veh Reg No: SLP9996R

Make/Model: HONDA HONDA
SHUTTLE 1.5G A

Chassis No: GK81007708

Engine No: L15B3539025

Reg. Date: 28/04/2017

TEL: 67143369

ATTN: Motor Claim Department

WS Ref: TP/ALLIANZ

Claim Type: Third Party

Accident Date: 16/08/2022

TP Veh Reg No: SJQ717H

Not Notified

83286.00

*Resurvey After Paint
4 days*

Estimate Repair Cost to Vehicle No : SLP9996R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	600.00	1 PC	600.00	✓
2 FRONT BUMPER RH SIDE RETAINER	8.00	1 PC	8.00	✓
3 FRONT BUMPER CLIPS	2.00	6 PCS	12.00	✓
4 FRONT RH FENDER	150.00	1 PC	150.00	✓
5 RH HEADLAMP	1,490.00	1 PC	1,490.00	✓
			2,260.00	
	Add 10%		226.00	2,486.00
Labour				
6 REMOVE & REFIX FRT BUMPER ASSY, FRT RH FENDER, RH HEADLAMP, KNOCK & REPAIR RH HEADLAMP PANEL AND REALIGN THE SAME	480.00	1 LA	480.00	400
7 PUTTY & REPSRAY ON FRT BUMPER, FRT RH FENDER, HEADLAMP PANEL	500.00	1 LA	500.00	400
				980.00

Total S\$ 3,466.00

Add GST @ 7% 242.62

Total Amount payable S\$ 3,708.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE