

# SNGAHTEE

MOTOR & PANEL SERVICE

孙亚弟汽车烧焊私人有限公司  
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4 lines) FAX: 62681429 | www.sngahtee.com  
sngahtee@singnet.com | UEN / GST REG. NO.: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ007560

DATE: 01/09/2022  
ACCIDENT DATE: 26/08/2022  
VEHICLE NO: GBJ4291Z  
CHASSIS/ENG.NO: JTFAT35Y70K213017  
VEHICLE MODEL: TOYOTA DYNA  
CLAIM NO: CC4/III22008507/ea3  
POLICY NO: SURVEYED BY LKK  
REMARK: 4291INDIA TP AGST  
XD4439L

| S/N.                            | QTY | UNIT | DESCRIPTION                          | PRICE    | DISC %  | DISC/MARKUP | TOTAL AMT       |
|---------------------------------|-----|------|--------------------------------------|----------|---------|-------------|-----------------|
| <b>** LIST PRICE **</b>         |     |      |                                      |          |         |             |                 |
| 1                               | 1   | PC   | REAR TAILLAMP ASSY(LH) ? X nn        | 381.90   | 25      | 286.43      | 286.43 X        |
| 2                               | 1   | PC   | REAR TAILGATE WITH HINGES ✓ DD       | 1,712.45 | 1339 25 | 1,284.34    | 1,284.34        |
| 3 (end panel)                   | 1   | PC   | REAR DECK FLOOR PANEL ✓ DD           | 1,712.45 | 898 25  | 1,284.34    | 1,284.34        |
| 4                               | 1   | PC   | EXHAUST MANIFOLD HEAT SHIELD ?       | 371.10   | 25 / BT | 278.32      | 278.32 ✓        |
| 5                               | 1   | PC   | EGR THROTTLE ? X / BT                | 1,217.10 | 25      | 912.83      | 912.83 ✓        |
| 6                               | 1   | PC   | FRT CABIN RR PANEL GLASS RUBBER X nn | 88.70    | 25      | 66.53       | 66.53 X         |
| SUB-TOTAL:                      |     |      |                                      |          |         |             | 4,112.79        |
| <b>** NETT PRICE **</b>         |     |      |                                      |          |         |             |                 |
| 1                               | 2   | PC   | REAR REVERSE SENSOR Shorted          | 380.00   | 10      | 342.00      | 200 ✓ 684.00    |
| 2                               | 1   | PC   | REAR TAILGATE TOYOTA STICKER NEC     | 180.00   | 10      | 162.00      | 162.00 ✓        |
| 3                               | 1   | PC   | REAR TAILGATE DYNA STICKER NEC       | 180.00   | 10      | 162.00      | 50 ✓ 162.00     |
| SUB-TOTAL                       |     |      |                                      |          |         |             | 1,008.00        |
| <b>** SPECIAL NETT PRICE **</b> |     |      |                                      |          |         |             |                 |
| 1                               | 1   | PC   | REAR NUMBER PLATE CUT                | 25.00    |         | 25.00       | 25.00 ✓         |
| 2                               | 1   | PC   | REAR STEP PANEL BT                   | 350.00   |         | 350.00      | 300 ✓ 350.00    |
| 3                               | 1   | PC   | REAR DECK GATE CHECKER PLATE BT      | 380.00   |         | 380.00      | 350 ✓ 380.00    |
| 4                               | 1   | PC   | REAR 13PAX STICKER NEC               | 20.00    |         | 20.00       | 20.00 ✓         |
| 5                               | 1   | PC   | REAR 70KM/H STICKER NEC              | 20.00    |         | 20.00       | 20.00 ✓         |
| 6                               | 1   | PC   | REAR DECK FLOOR CHECKER PLATE BT     | 1,800.00 |         | 1,800.00    | 1500 ✓ 1,800.00 |
| SUB-TOTAL                       |     |      |                                      |          |         |             | 2,595.00        |

PAGE: 1 of 2

JANICE

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:  
The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.  
Quotation is only valid for 14 days.

# SNGAHTEE

MOTOR & PANEL SERVICE

孙亚弟汽车烧焊私人有限公司  
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4 lines) FAX: 62681429 | www.sngahtee.com  
sngahtee@singnet.com | UEN / GST REG. NO.: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET  
IOB BUILDING SINGAPORE 049711

ATTENTION:  
CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ007560

DATE: 01/09/2022  
ACCIDENT DATE: 26/08/2022  
VEHICLE NO: GBJ4291Z  
CHASSIS/ENG.NO: JTFAT35Y70K213017  
VEHICLE MODEL: TOYOTA DYNA  
CLAIM NO: CC4/III22008507/ea3  
POLICY NO: SURVEYED BY LKK  
REMARK: 4291INDIA TP AGST  
XD4439L

| S/N.                     | QTY | UNIT | DESCRIPTION                                                                                                          | PRICE     | DISC % | DISC/MARKUP | TOTAL AMT |
|--------------------------|-----|------|----------------------------------------------------------------------------------------------------------------------|-----------|--------|-------------|-----------|
| <b>** WORK LABOUR **</b> |     |      |                                                                                                                      |           |        |             |           |
|                          |     |      | TO KNOCK FRT CABIN REAR PANEL, FRT DOOR REAR PANELx2, REAR SIDE GATE END PORTION, WELD, REMOVE & REPLACE ABOVE PARTS | 1200.00   | 1000   | ✓           | 1,200.00  |
|                          |     |      | TO SPRAY PAINTING ON FRT CABIN REAR PANEL, FRT DOOR REAR PANELx2, RR SIDE GATE END PORTION, TAILGATE, RR FLOOR PANEL | 1200.00   | 600    | ✓           | 1,200.00  |
|                          |     |      | TO LIFT UP REAR DECK (require take photo dismantle)                                                                  | 500.00    |        |             | 500.00 ✓  |
|                          |     |      | TO REMOVE & REFIT FRT CABIN RR PANEL GLASS, INNER TRIM                                                               | 80.00     | 50     | ✓           | 80.00     |
|                          |     |      | TO CHECK WIRING                                                                                                      | 30.00     |        |             | 30.00 ✓   |
|                          |     |      | TO APPLY ANTI RUST COATING                                                                                           | 120.00    | 30     | ✓           | 120.00    |
|                          |     |      | TO TOWING                                                                                                            | 70.00     |        |             | 70.00 ✓   |
|                          |     |      |                                                                                                                      | SUB-TOTAL |        |             |           |
|                          |     |      |                                                                                                                      | 2280      |        |             |           |
|                          |     |      |                                                                                                                      | = 7775.90 |        |             |           |

Steve (LKK)  
01/09/22  
Without Prejudice  
L/S  
Resurvey After Spray  
9 days

~~\*\*\* To Remove & Refit RR Canopy Set - 200 ✓~~  
~~EGR Switch - RR~~

JANICE ~~Chassis frame~~ PAGE: 2 of 2  
~~EGR Steel pipe~~ (Labour)  
SUB-TOTAL: S\$ 10,915.79  
ADD 7% GST. S\$ 764.11  
GRAND TOTAL: S\$ 11,679.90

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

**Disclaimer clause:**

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.  
Quotation is only valid for 14 days.

# SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

AXA Ref :

Date : 23/09/2022

ATTN:THE MOTOR CLAIMS DEPT  
INDIA INTL INSURANCE PTE LTD

## SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No. GBJ4291Z  
Date of Accident 26-Aug-22  
Type of Claim TP INDIA  
Survey By \_\_\_\_\_

Model / Year TOYOTA DYNA  
Policy No. \_\_\_\_\_  
Prepared By SHARON  
Chassis No. \_\_\_\_\_

| S/NO | Description                   | Qty | Cost Price          | Amount                  |            |
|------|-------------------------------|-----|---------------------|-------------------------|------------|
| 1    | EGR SWITCH                    | 1   | \$ 181.52           | \$ 181.52               | ✓ BR       |
| 2    | EGR STEEL PIPE                | 1   | \$ 238.99           | \$ 238.99               | ✓ BT       |
|      |                               |     |                     | \$ 420.51               |            |
|      |                               |     | LESS 25%            | \$ <del>45.28</del>     |            |
|      |                               |     |                     | \$ <del>375.13</del>    | 315.38     |
| 3    | REAR CHECKER PLATE RIVET      | 30  | \$ 2.00             | \$ 60.00                | SNETT 40 ✓ |
| 4    | TO REMOVE FIX REAR CANOPY SET | 1   | \$ 300.00           | \$ 300.00               | 250 ✓      |
| 5    | TO STRAIGHTEN CHASSIS FRAME   | 1   | \$ <del>50.00</del> | \$ 500 <del>50.00</del> | 300 ✓      |
|      |                               |     |                     | \$ 785.13               |            |

supp - 905.38

main estimate - 7775.90

8681.28

L/S - 6945.02

= 6950

total \$ 9451.96  
less 20% = \$ 7561.56  
at \$ 7550 Lump sum  
ok? pls revert.  
Sharon 23/9/2022