

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 17/09/2022

User ID : PohSuan

Section A - Accident Details

Registration Number	SHB5947E
Case Reference Number	TAX/08/22/2083
Registration Date	12/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TIA CHEONG SENG
Type of Accident	Side Swipe
Accident Date and Time	30/8/2022 9:30 AM
Accident Reported Date and Time	31/8/2022 10:39 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116103
Special Instruction to ARC, if any	BP/ LEFT FRONT PORTION
Prepared Date and Time	31/8/2022 1:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$8,008.31	\$1,860.65
Total Other Cost	\$380.00	\$100.00
TOTAL COST	\$10,180.31	\$2,760.65
Lump Sum Total	\$10,200.00	\$2,750.00 (L/S)
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / China Taiping
ARC / Surveyor Sign Off Date	02/09/2022 5:24 PM	02/09/2022 4:08 PM
Signature		
Remarks		resurvey after repair / lump sum

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2209-0150	Invoice Number	
Quotation Date	14.09.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$400.00 ✓
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
RESPRAY WHEEL CAP	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	\$100.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check
		5144447010	COVER, ENGINE UNDER SIDE LH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		8122047020	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Check
		8118547691	UNIT , HEADLAMP , LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check
		8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given
		5380247100	FENDER SUB-ASSY, FR , LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		5387647110	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Check
		5385247041	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given
		5380847020	SEAL SUB-ASSY, LH	0.00	\$50.20	0.00	\$0.00	Replace	Not Given
		5382847070	PROTECTOR, FR FENDER LH	0.00	\$90.40	0.00	\$0.00	Replace	Not Given
		4260247180	CAP SUB-ASSY, WHEEL	1.00	\$175.80	25.00	\$131.85	Replace	Replace
		4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given

✓ De

X nn

X nn

✓ Nec

X } nn

X } nn

✓ BT

✓ Nec

X } nn

X } nn

X } nn

✓ SCR

X } nn

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/09/2022

User ID : PohSuan

		43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given
Total					\$8,402.14		\$1,254.24		

Xⁿⁿ

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace
		81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		53112472 40	GRILLE, RADIATOR	1.00	\$183.90	25.00	\$137.93	Replace	Replace
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
Total					1,246.70		1,071.57		

√
√
√
√ } CRA

	2,325.81	
	-20%	
	1860.65	L/S \$2,750/-
+	400.00	
+	500.00	
	2,760.65	