

Case Details

Case Reference Number :

TAX/08/22/2083

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5947E

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-19226-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 30/08/2022 01:30 AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	de /
Standard	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Check	? for
Standard	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	Xnn
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	ne /
Standard	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check	? Xnn
Standard	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	? Xnn
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Not Give	Xnn
Standard	Main			FENDER SUB-ASSY, FR, LH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace	st /
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.68	Replace	1	39.68 39.68	Replace	ne /
Standard	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Check	? Xnn
Standard	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	Xnn
Standard	Main			SEAL SUB-ASSY, LH	1	50.20	50.20	25.00	37.65	Replace	0	0	Not Give	Xnn

Total Spare Part Cost 6,936.76

Surveyor Total 1,254.23

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,216.89

Final Sur Total 1,003.38

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			PROTECTOR, FR FENDER LH	1	90.40	90.40	25.00	67.80	Replace	0	0	Not Give	Xm
Standard	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	25.00	131.85	Replace	1	131.85	Replace	scr
Standard	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	Xm
Standard	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xm
Standard	Main			HUB & BEARING ASSY, RH & LH	1	554.20	554.20	25.00	415.65	Replace	0	0	Not Give	Xm
Total Spare Part Cost									6,936.76	Surveyor Total		1,254.23		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									5,216.89	Final Sur Total		1,003.38		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	676.00	400	
Total:			676.00	400.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	RESPRAY WHEEL CAP	180.00	0	Xm
4	Main	TO RESPRAY RIM	180.00	0	Xm
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	Xm
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
Total:					

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>xm</i>	
Total:			380.00	100.00 /	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,216.89	1,003.38
Total Labour Cost	676.00	400.00
Total Spray Painting	1,116.00	400.00
Other	380.00	100.00
Overall Total	7,388.89	1,903.38
Lump Sum Repair Option	☐	☒
Lump Sum Total	7,400.00	1,900.00
Surveyor Approved Amount		1,900.00
No of Repair Days*	5	4
Remarks	-	resurvey after repair / lump sum
Surveyor Name		Rasul
Signature		
Survey Date	31/08/2022	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: