

MY CAR CONSULTANT PTE LTD
 (Co Reg. No. 201605878Z)
 60 JALAN LAM HUAT, CARROS CENTRE
 #05-68 (S737869)

TO	: ALLIANZ	DATE	: 31-Aug-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJL8375J
ADDRESS	:	MODEL	: HONDA FIT
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>bu</i>	1	\$ 998.00	\$ 998.00
2	TAIL GATE STOPPER <i>ne</i>	1	\$ 28.50	\$ 28.50
3	TAIL GATE INNER LOCK <i>int</i>	1	\$ 289.00	\$ 289.00
4	TAIL GATE WIPER MOTOR <i>x na</i>	1	\$ 589.00	\$ 589.00
5	TAIL GATE ABSORBER <i>x na</i>	2	\$ 136.20	\$ 272.40
6	TAIL GATE HINGE <i>x na</i>	2	\$ 31.00	\$ 62.00
7	TAIL GATE DETECTOR <i>x na</i>	1	\$ 154.00	\$ 154.00
8	TAIL GATE WEATHER STRIP <i>ne</i>	1	\$ 154.00	\$ 154.00
9	TAIL GATE INNER TRIM <i>cm</i>	1	\$ 258.00	\$ 258.00
10	TAIL GATE WINDSCREEN MOULDING <i>ne</i>	1	\$ 110.00	\$ 110.00
11	TAIL GATE OUTER GARNISH <i>x na</i>	1	\$ 184.00	\$ 184.00
12	TAIL GATE OUTER GARNISH LOGO <i>x na</i>	1	\$ 58.00	\$ 58.00
13	TAIL GATE REFELCTOR <i>x na</i>	2	\$ 311.00	\$ 622.00
14	TAIL GATE EMBLEM "FIT" <i>ne</i>	1	\$ 35.00	\$ 35.00
15	REAR BUMPER <i>de</i>	1	\$ 659.00	\$ 659.00
16	REAR BUMPER SIDE GARNISH <i>? x na</i>	2	\$ 121.00	\$ 242.00
17	REAR BUMPER CENTER GARNISH <i>? x na</i>	1	\$ 124.00	\$ 124.00
18	REAR BUMPER SIDE RETAINER <i>ne</i>	2	\$ ^{@35.20} 45.00	\$ 90.00
19	TAIL LAMP <i>? cm</i>	2	\$ ^{@338.10} 489.00	\$ 978.00
20	REVERSE SIREN <i>x na</i>	1	\$ 121.00	\$ 121.00

796
 ✓
 186.30
 X
 X
 X
 X
 X
 148.40
 190.20
 ✓
 X
 X
 X
 ✓
 490
 X
 X
 70.40
 676.20
 X

3	TUFF COAT	\$180.00	60
4	WIRING CHECK	\$60.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$300.00	X na
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$250.00	60
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$200.00	X na
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$120.00	/
9	TRANFER TAILGATE MECHANISM	\$80.00	60
10	CONDUCT WATER LEAKAGE TEST	\$100.00	30

TOTAL

\$4,290.00

1960

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,088.58
 TOTAL LABOUR COST : \$ 4,290.00
 TOTAL REPAIR COST : \$ 16,378.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3249.52
 450.00
 1960.00

 5659.52
 20%
 4527.61

Rasul
 Hp 90010068
 7 days
 L/S
 31/08/22 @ 1630
 Reg after repair

L/S - \$4,500 / 7 days