



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

TP A x A.

Xiao Tony

Page No. 1

Vehicle No. SCN5277B

MERCEDES BENZ S300L

WDD2211542A309312

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>		3158 2842.20	1850.00		✓	
1	RERA BUMPER Distorted		128.00		✓	
2	REAR BUMPER SIDE HOLDER and		246.00		✓ 123.	
3	REAR BUMPER SIDE MOULDING @123 Replaced		723.00		✓	
4	TAILLAMP Lt.		3280.00		X.	
5	REAR FENDER Key		286.00		✓	
6	REAR FENDER INNER SHIELD dehd		48.00		✓	
7	REAR FENDER AIR VENT cut		1380.00		X.	
8	REAR WHEEL RIM 3 new		183.00		X.	
9	REAR WINDSCREEN MOULDING					
		less	10%	8124.00	10%	
				812.40		
				7311.60		
<u>SPECIAL NETT ITEMS</u>		330	50.00		✓	
1	REAR BUMPER CLIPS me		30.00		✓	
2	REAR FENDER INNER SHIELD CLIPS me		60.00		X	
3	REAR WINDSCREEN SEALANT me me		350.00		X 250	
4	REAR TYRE Lt					
		Total Parts	490.00			



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Page No. 2

Vehicle No. SCN5277B

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	PANEL BEATING	800.00	400
2	SPRAY PAINTING	800.00	500
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	30
5	TO REMOVE UPHOLSTERY	150.00 X	
6	TO REMOVE REAR WINDSCREEN	180.00 X	
7	TO PERFORM WHEEL ALIGNMENT	150.00 X	80
	Labour Total :	2280.00	
TOTAL (PARTS & LABOUR):		10081.60	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4212.20
L/S 3350
03 Days