



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC Life (Singapore) Pte. Ltd.

Date: 31/07/2023

Survey Details:

| | |
|---------------------|------------------------|
| Date of loss | 28-Aug-2022 |
| Date of appointment | 30-Aug-2022 |
| Date of survey | 31-Aug-2022 |
| Location of survey | AUTO UNITED SG PTE LTD |

Vehicle Details:

| | |
|----------------------|-----------------------------|
| Claim Type: | THIRD PARTY CLAIM |
| Vehicle number | SCN5277B |
| Make and Model | MERCEDES BENZ S300L - 2997c |
| Date of registration | 26-Mar-10 |
| Market Value | \$ 86,000.00 |
| Parf Rebate | \$ 26,800.00 |
| Nett Loss | \$ 59,200.00 |

Repair details:

| | |
|------------------|-----------|
| Initial Estimate | 10,081.60 |
|------------------|-----------|

Proposed/Revised repair cost:

| | |
|--------------------------------|--------------------|
| Parts | \$ 3,172.20 |
| Check items (estimate) | \$ - |
| Labour | \$ 1,040.00 |
| Total | \$ 4,212.20 |
| Lump Sum(if applicable) | \$ 3,350.00 |

| | |
|---------------------------|-----|
| Number of days for repair | 3.0 |
|---------------------------|-----|



Remarks:

OID intends to filter to right lane and accidentally hit onto TP who was in front of OID.

Mandate:

| Liability(TP) | 100% | |
|--|--------------------|--------------------|
| Proposed repair cost (WITH GST) | \$ 3,618.00 | \$ 3,618.00 |
| Loss of use (5DAYS X \$100.00) | \$ 500.00 | NIL |
| Loss of rental (5DAYS X \$160.00)(w/GST) | NIL | \$ 856.00 |
| Loss of income | NIL | NIL |
| LTA search fees | \$ 7.45 | \$ 7.45 |
| Others | \$ 31.00 | \$ 31.00 |
| Proposed Total | \$ 4,156.45 | \$ 4,512.45 |