

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

© /OptimaWerkz

Date: 31/08/2022
Vehicle No: SNB3375Y
Model: TOYOTA PRIUS
Chassis: JTDKB3FU603093295 - 2020
Reg.Year: 2021

Third Party Insurer: AIG ASIA
Third Party Veh No: SMH8194A
Date of Accident: 12/07/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		REPAIR
2	REAR FENDER RH	1		REPAIR
3	REAR DOOR RH	1		REPAIR
4	REAR RIM COVER RH	1		REPAIR
SUB TOTAL				\$0.00
LESS 25%				\$0.00
PARTS TOTAL				\$0.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		AN \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$300.00 1501

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$700.00 4001

TO TUFF KOTE & UNDERSEAL MATERIALS. AN \$100.00 X

LABOUR TOTAL \$1,100.00

KIT TOTAL \$1,150.00

Not withstanding
Painting After Pain
@ 550h 2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554501
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Acknowledged by Repairer (Insurance Claims)

Signature: [Signature]
Date: [Date]

