



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016	
		Document No. 0		
		Document Date 25/11/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	49546	17266	72/OD/GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DHOM120061172100 ACC DATE:30.08.2022 TOW IN:30.08.2022 EXCESS:\$500 DATE-IN:30.08.2022 DATE SURVEY:01.09.202 2NO OF REPAIR DAYS:20 WORKING DAYS BY:LKK-STEVE AUTHORIZED ON:05.09.2				50.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT	0742			400.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP	0742			122.40
4	S	BP-SUBLET R/I DASHBOARD ASSY TO FAC REPAIR	0742			1440.00
5	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	0742			720.00
6	S	BP-SUBLET REPLACE ROOF LINING	0742			720.00
7	S	BP-SUBLET R/I AC BLOWER SYSTEM TO FAC REPAIR	0742			720.00
8	S	BP-SUBLET R/I WIRE HARNESS ASSY TO FAC REPAIR	0742			720.00
9	S	BP-SUBLET REPLACE FRONT WINDSCREEN GLASS	0742			462.00
10	S	BP-SUBLET REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR	0742			360.00
11	S	BP-SUBLET R/I CABIN ASSY TO FAC REPAIR	0742			2160.00
12	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00
13	S	BP-SUBLET REPLACE ACC DAMAGED PARTS	0742			7200.00
14	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS	0742			2950.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016
	Document No. 0	
	Document Date 25/11/2022	

Year	Model	Variants	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	49546	17266	72/OD/GBL4078M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	S	BP-SUBLET SUPPLY COMPANY DOOR BLACK STICKER -1PC	0263			50.00
16	Z	BP-BKT SUPPLY IU BRACKET				26.00
17	V	EXC Excess element of insurance repair to be paid by the insured party	8888			-500.00
18	1	T75315-37080 ORNAMENT, RADIATOR	1.00	76.20		76.20
19	2	T75311-25100 PLATE, FR NAME, NO.1	1.00	68.70		68.70
20	3	T53111-37A01 B1 GRILLE, RADIATOR	1.00	644.30		644.30
21	4	T67771-37040 RETAINER, DOOR TRIM	10.00	6.60		66.00
22	5	T53115-37080 BRACKET, RADIATOR	1.00	26.90		26.90
23	6	T63111-37120 PANEL, ROOF	1.00	667.80		667.80
24	7	T63132-37074 PANEL, WINDSHIELD	1.00	196.00		196.00
25	8	T63141-37061 REINFORCEMENT, ROOF	1.00	184.20		184.20
26	9	T61131-37083 PILLAR, FR BODY,	1.00	442.50		442.50
27	0	T61108-37031 REINFORCEMENT	1.00	315.80		315.80
28	1	T61023-37041 PILLAR SUB-ASSY, FR	1.00	378.90		378.90
29	2	T61455-37010 RETAINER, FR STEP,	1.00	28.20		28.20
30	3	T61245-37010 REINFORCEMENT, ROOF	1.00	39.60		39.60
31	4	T61035-37070 BRACKET SUB-ASSY,	1.00	129.20		129.20
32	5	T61231-37050 RAIL, ROOF SIDE,	1.00	197.90		197.90
33	6	T61611-37142 PANEL,@	1.00	689.80		689.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO1	M/S Lim Bs Enterprise Plastercell 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016	
		Document No.		
		0		
		Document Date		
		25/11/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	49546	17266	72/OD/GBL4078M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	7	T61451-37010 PLATE, STEP, LWR RH	1.00	48.00		48.00
35	8	T56111-37120 GLASS, WINDSHIELD	1.00	1697.40		1697.40
36	9	T56121-25040 WEATHERSTRIP,	1.00	399.40		399.40
37	0	T55078-37110 COVER SUB-ASSY, FR	1.00	337.00		337.00
38	1	T55738-37080 PROTECTOR, FR PANEL	1.00	98.70		98.70
39	2	T55735-37021 REINFORCEMENT, COWL	1.00	43.10		43.10
40	3	T53821-37100 BRACKET@	1.00	67.50		67.50
41	4	T53813-37170 B0 PANEL, FR SIDE, RH	1.00	353.40		353.40
42	5	T55330-37210 REINFORCEMENT ASSY,	1.00	678.20		678.20
43	6	T63310-37611 B0 HEADLINING ASSY,	1.00	1935.30		1935.30
44	7	T90467-06048 B9 CLIP	10.00	3.00		30.00
45	8	T67610-37090 B6 PANEL ASSY, FR DOOR	1.00	531.70		531.70
46	9	T67861-37021 WEATHERSTRIP, FR	1.00	221.40		221.40
47	0	T67863-37011 WEATHERSTRIP, FR	1.00	110.40		110.40
48	1	T68161-37011 WEATHERSTRIP, FR	1.00	123.20		123.20
49	2	T67495-37010 COVER, FR DOOR FR	1.00	60.00		60.00
50	3	T68141-37030 RUN, FR DOOR GLASS,	1.00	263.40		263.40
51	4	T68101-37100 GLASS @	1.00	805.10		805.10
52	5	T90541-09031 CUSHION	4.00	10.80		43.20
53	6	T68710-37020 HINGE ASSY, FR DOOR,	1.00	119.20		119.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUOI1	M/S Lim Bs Enterprise Plastercell 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016	
		Document No. 0		
		Document Date 25/11/2022		

Year	Model	Variants	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	49546	17266	72/OD/GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
54	7	T68730-37010 HINGE ASSY, FR DOOR,	1.00	119.20		119.20
55	8	T87819-25010 LENS, INNER RR VIEW	1.00	15.40		15.40
56	9	T90467-10188 CLIP	2.00	3.00		6.00
57	0	T55785-37050 PAD, FR PANEL COVER	1.00	3.00		3.00
58	1	T90467-10188 CLIP	2.00	3.00		6.00
59	2	T87910-25040 MIRROR ASSY, OUTER	1.00	352.70		352.70
60	3	T85212-37081 BLADE, FR WIPER, RH	1.00	91.90		91.90
61	4	T81110-37660 HEADLAMP ASSY, RH	1.00	1272.30		1272.30
62	5	T75362-35090 PLATE, FR FENDER	1.00	54.70		54.70
63	6	T55700-37350 COWL ASSY	1.00	1291.80		1291.80
64	7	T53866-37042 SEAL, FR FENDER TO	1.00	50.50		50.50
65	8	T53827-37010 PROTECTOR, FR FENDER	2.00	48.80		97.60
66	9	T55312-37011 B0 PANEL, INSTRUMENT,	1.00	302.70		302.70
67	0	T45252-37050 C0 TUBE, STEERING (supp) CRU	1.00	109.80		109.80 ✓
68	1	T68610-37030 CHECK ASSY,@	1.00	198.60		198.60
69	2	T69310-37080 LOCK ASSY, FR DOOR,	1.00	341.40		341.40
70	3	T69801-37063 REGULATOR SUB-ASSY,	1.00	385.10		385.10
71	4	T87210-37100 CASE ASSY, AIR	1.00	365.40		365.40
72	5	T55301-37090 C0 PANEL SUB-ASSY,	1.00	1090.40		1090.40
73	6	T62313-37080 B0 TRIM, FR DOOR	1.00	117.80		117.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016	
		Document No. 0		
		Document Date 25/11/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	49546	17266	72/OD/GBL4078M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
74	7	T51771-25021 PLATE, STEP@	1.00	327.70		327.70
75	8	T62210-37010 B0 GARNISH ASSY, FR	1.00	92.40		92.40
76	9	T81973-37010 RETAINER, SIDE TURN (supp) NEC	1.00	4.40		4.40
77	0	T87010-37230 UNIT ASSY, AIR	1.00	2895.60		2895.60
78	1	T67001-25051 PANEL SUB-ASSY, FR	1.00	1941.80		1941.80
79	2	T87810-37091 C0 MIRROR ASSY, INNER	1.00	136.10		136.10
80	3	T67913-37010 B1 PLATE, FR DOOR	1.00	234.10		234.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			41,802.40
	Please acknowledge receipt of vehicle	Parts 24,022.00	GST 7.00% 2,926.17
		Labour 76.00	Less 0.00
		Sublet 18,204.40	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 44,728.57

Customer Copy